JAN 21 1999

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

Corner Code # Mackinac County Located in: T43N R2W 1. Public Land Survey L-13 (Same Corner T44N R2W Chippewa County) R Т R T Т R S 2. Property Controlling Т R S in Section S Т R Miscellaneous S Property in Sec.

RECEIVED & FILED DIANE FRANKOVICH MACKINAC COUNTY REGISTS, OF DEEDS

DEC 3 0 1998 PM 7[8[9]10]11[14]1]2[3]4[5]6

Register of Deeds Stamp & File Number

В

5

6

8

q

10

11 12

1.3

<u>۲۱ الان</u>ان " THE NIAGIGNAL

, Recorded Plat 4. Lot No. 5. Private Claims

SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING

HELD ON_ 11-50-48 NEV

I, Keith R, Waters, in a field survey on October 30, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-1 1/4 Corner Common to Section 1, T43N, R2W & Section 36, T44N, R2W

1840 - Original corner established by William A. Burt was a 6" Fir. Witness: Sugar 6, NORTH 31/2 links.

1972 - Corner position is shown on a Certificate of Survey, liber 1, pages 415-417, Mackinac County records.

1995 - LCRC, liber 9, page 249, Chippewa County corner records. Keith R. Waters, P.S. 33142, corner being perpetuated as part of the Chippewa County Remonumentation Program. Found and accepted a ½" i.d. iron pipe at the corner location. Replaced the bent pipe with a 3/4" rebar with a plastic Chippewa County Remonumentation cap. Note that this position appears to be in conflict with as shown in above mentioned Certificate of Survey. Witnesses:

Nail and tag #22428 in side of Power Pole, S14°E 53.45'

Nail and tag #33142 in side of 5" Elm, S65°W 72.22' Nail and tag #33142 in side of 7" Elm, N20°W 29.08'

Nail and tag #33142 in side of 9" Spruce, N14°E 30.41'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Mackinac County Remonumentation Program. Found the 3/4" rebar with plastic Chippewa County Remonumentation cap and all four witness objects as called for in above mentioned Chippewa County LCRC.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 3/4" rebar with a plastic Chippewa County Remonumentation cap at the corner location, which falls approximately 3 feet north of the centerline of an east-west gravel road (Townline Road), on the extension of an old fence line to the south. Witnesses:

Nail and tag #22428 in side of Power Pole, S14°E 53.45'

Nail and tag #33142 in side of 5" Elm, S65°W 72.22' Nail and tag #33142 in side of 7" Elm, N20°W 29.08'

Nail and tag #33142 in side of 9" Spruce, N14°E 30.41'

Note: Trees are blazed, bearings are compass bearings corrected for declination.

ATE OF MICHIGAN KFITH B. WATERS **PROFESSIONAL** SURVEYOR No. 33142 n OFESSIONAL

Signed by Keith R. Water

12-23-98

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995