

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

1 Corner

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>44</u> N. <u>2</u> , R. <u>7</u> E. <u>W.</u>		G-7
2. PROPERTY CONTROLLING IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-29, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Sec. Cor. 15-16-21-22, set by H. Brevoort Jr., D.S. in 1845. Bearings were:  
Sugar 14", S16°W, 12 lks. & Sugar 14", N64°W, 31 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Re-established Section Corner by proportionate measure bet. an original corner 1 mile North, corners to South and in line with an old grade to South, reported to be on the Section line. Found a cave entrance, recorded as 1.58 chains West of corner, at North edge of a Quarry excavation.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is in the Quarry excavation. No monument set at the Corner. Placed witness Irons; S0° 54'W, 215.0' from the corner and N0° 42' E, 1,461.67' from the corner.

Witness Iron, S0° 54'W, 215.0' from Section Corner: 36" T-Iron, bearings to T-Iron: 10" Cherry, S38°W, 47.3' & 5" Aspen, N70°W, 20.4' & 5" Balsam, N85°E, 20.8'.

Witness Iron, N0° 42'E, 1,461.67' from Section Corner: 36" T-Iron, bearings to T-Iron: 8" Balm-of-gilend, S50°E, 15.85' & 14" R. Maple, N28°W, 28.02'.

SIGNED BY

Billy D. Buckler  
BILLY D. BUCKLER

DATE 5-5-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY


DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)



SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET