

71

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac

(County)

Located in:

Corner Code #

**1. Public Land Survey**

T 44N R 7W 67

T 44N R 7W 69

T R

T R

**2. Property Controlling in Section**

S T R

S T R

**3. Miscellaneous Property in Sec.**

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Jul 16 1997

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(67) Corner common to Sections 15-16-21-22. Corner Reestablished in 1981 by Billy D. Buckler, RLS and remonumented in 1989 by Gerald L. Higgins, RLS: "Set corner from 2 witness irons set and recorded by Billy D. Buckler L.S. 88887 on 5-5-81. Set DNR monument T-iron N 0 deg. 42' E 1461.67', T-iron S 0 deg. 54' W 215.0', 6" W. Birch N64W 24.2', 6" Aspen S40W 40.0'".

(69) Corner common to Sections 21-22-27-28. Corner reestablished in 1979 by Billy D. Buckler, LS, and recorded in 1980. Corner monument is 36" T-iron, buried. Witnesses to corner: 15" J. Pine N78E 41.6', 16" R. Pine S58E 36.0', Found north edge of a pine plantation, 12' to north, to east of here.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(67) Recovered the 1989 monument, a 1" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, in good condition, and at record bearing and distance from the 1989 W. Birch and Aspen NBTs. Left the monument in place and marked additional witnesses as described below. Corner recovered and witnessed by T.Stark, Newberry District Office.

(69) Recovered the 1979 monument, as described, in good condition, and at record bearing and distance from the R. Pine NBT. The J. Pine has been cut. Left the monument in place and marked new accessories as described below. Corner recovered and witnessed by T.Stark, Newberry District Office.


**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(67) Found 1" pipe with 4" MDNR cap. Blazed, scribed, and set measuring nails in the following:

7" W. Birch N64W 24.75' "S16"  
10" Aspen S41W 40.6' "S21"  
3" Aspen N87E 8.7' "S15 NBT"  
12" Aspen S20E 12.0' "S22 NBT"

Placed a 4" squared cedar post adjacent. Bearings are magnetic.

(69) Found T-iron, buried. Blazed, scribed, and set measuring nails in:  
24" R. Pine S54E 36.8' "S27"  
6" W. Birch S60W 29.2' "S28 NBT"  
8" W. Birch N88W 25.9' "S21 NBT"  
4" W. Birch N54W 32.2' "S21 NBT"  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski

Surveyor's Michigan License No. 33986

Date 2/24/98

For the Michigan Department of Natural Resources - Forest Management Division