

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Mackinac

(County)

Located In:

Corner Code #

1. Public Land Survey

T 44NR 7W

D11

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S 32

T 44NR 7W

9

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File  
Number

4. Lot No. , Recorded Plat

5. Private Claims

Nov 01 2005

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D11) Quarter corner common to Sections 29-32. 1845 - Established by H. Brevoort, Deputy Surveyor: West corrected between Sections 29 & 32 ...40.145 Set 1/4 Section post. Tamarack 4 S76E 33 links, Tamarack 5 N55W 55 links. ...80.29 Section corner (9-Sec. 32) East 1/16 corner, Section 32. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D11) The original post and accessories were not recovered. Reestablished the corner by single proportionate measurement to the original GLO record and on the section line between Section corners 2663.03' East and West.  
(9-Sec. 32) Established the corner midway and on a straight line between Quarter corner 1332.22' East and Center of Section (unmonumented) 1332.22' West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

(D11) Set 1"IDx36" I.pipe with 4" alum.  
MDNR cap. Set measuring nails in:  
5" B.Spruce S56W 11.42' mrkd "1/4S NBT"  
5" B.Spruce N12W 10.03' do  
7" B.Spruce S84E 24.05' do  
12" W.Pine S18W 19.65' do  
Bearings are magnetic. Distances are to nail with tag.

(9) Set 1"IDx32" I.pipe with 4" alum.  
MDNR cap. Set measuring nails in:  
4" Cedar S72W 118.32' mrkd "E1/16 BT"  
8" Aspen N46W 36.4' do  
9" Cedar S28W 224.85' do  
Bearings are magnetic. Distances are to nail with tag. The corner falls in NW cor. of dry lake bed.



Signed by

Stephan J. Szyszkoski

Date

1/26/06

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995