## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			Mackinas		COUNTY	
		T	AAN	R .	8-9N	
DESCRIPTION OF CORNER Sec. Cer. comme	a to Secs. 6	-7-1-12				
CORNER MONUMENT 1" pipe with 4" alumin	ш сар.		····	<del></del>		
DATE MONUMENT PLACED AND WITNESSED	7-68				<del></del>	
WITNESSES TO CORNER 7" Soft Maple	(S6 NBT) N5	6°E 5.0	<u> </u>			
N 8" Seft Maple	(S12 NBT) S	3 <b>9°</b> W 10.	.21			
8" Hard Maple	(ST NBT) S	47 <sup>0</sup> x 17.	,00			
AND			•			
CIRCLE CORNER REGISTERED	· · · · · · · · · · · · · · · · · · ·			-		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as found by Marcus Schaaf, R.L.S. in 1933. Found remains of wood stake in ground at proper distance from Schaaf's lines from north and east.

Corner lies 95° south of read.

SURVEYOR'S SEAL

SIGNED

Billy Cluckler

Billy D. Buckler

DATE \_\_\_

3-18-69

**DISTRIBUTION:** 

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing