LAND CORNER RECORDATION CERTIFICATE 93 DEC 22

		LAND	CONNE	N RECORDATION CENTIF	CALE 33 DEC 22	. HII 2"	UĢ		
_		Filing	Require	ment of Act 74, Mich. P.A.	. 1970 CARMELL	A CARATH	311		
FOI	corners in			t.	DEGISTE	R OF DEED) (C		
	MACOMB (County)	Located In:	IO TAID	Corner Code ##	MACOMB	COUNTY	ΜT		
	. (Geunty)	STERLIN	NG TVVP.		MOONE	occiri i , i	1.4		
1.	Public Land Survey	т 2N R	12E	K-4					
	, , , , , , , , , , , , , , , , , , , ,	T R			0	04 04 s	ഹഹ		
		T R			LIBERU	6161P	122	,	
	,	T R							
2.	Property Controlling	S T R							
	in Section	S T R							
3.	Miscellaneous	S T R			Register of Deed	ds Stamp &	File N	umbe	r
	Property in Sec.	S T R							
,	l et blo	Departed Blot							
					A B C	D E F G	H I	JK	L
υ.	riivate Olaiiiis				2 6	54	_ ¦ _	-2- -	_{ .
					3		<u> </u>		
					4 7		10	_, ,	
ı	BRUCE ANTCLIFF	, in a field survey on _	NOV	EMBER 22. 93	. 5		Ĭ	ïĬ	
do	hereby certify that under re	equirements of P.A. 74, Mic	higan P.A. c	of 1970, the corner points mention				ŢŢ	
				rules therefore as required in t	he _	17———16———	15 - -	-14	—13-
				nent of the Interior, Bureau of La points mentioned in lines 3, 4 and	""				\neg
	·			Land Surveyors or by a Decree of	ita [ˈiˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈˈ	20 21 - 1	-22-	-23-	—24
				onumented, recovered, found	as 9	 		1 1	\neg
exp	ressed below:				10 30	29 28	-27-	-26	25- I
NO	TE: Not more than 4 of	corners, all in the same	e town and	d range, may be recorded	11	 		\dashv	\dashv
	on this certificate	.			12 31	32 33	34	-35-	—3¦6-
					13				
Α.	·			or subsequent restoration:	1.000 (4000) 477	SE D400 4 101 D	455461	nav	
	GLO-Post, NO WITS. REMAIN			918,P55-PK NAIL IYDRANT, NWLY, 78.72	LCRC (1988) L479 N&T N FACE UTII			BOX	
	EDISON NOTES(1957)-3/4" IR	ON PK	AT UTILITY I	POLE, EAST, 31.78'	TOP CENTER HY	DRANT, NW, 7	78.70 '		
	EDISON NOTES, (1960)-5/8" R			TILITY POLE, SE'LY, 155.30' AIN LINK FENCE, WEST, 60.24'	PAINTED "+" N EI PK IN SE FACE 8				
								_	
	EDISON NOTES (1961)-PK NAI		LCRC (1979) L3106,P516-1/2" REBAR TOP CENTER HYDRANT, N32W, 78.75"		LCRC (1989) L477 PK&T N FACE UT			л.	
			NCE POST,		TOP CENTER HY	DRANT, NW, 7	0.70		
		N8	T N SIDE WO	OOD POLE, \$85E, 31.80'	PK IN S FACE 16" N&T IN N FACE U			.75'	
					1401 1111111000	2112	Z		3
					C. F. C	FAX	0	i	ŞI
В.	Description of corner of FOUND 5/8" REBA	evidence found and/or AR/MON_BOX	method a	oplied in restoring or reestab	lishing corner:	1524	_		3
						SES	A	7	≤
				D BY MCRC. THE PREVIOU		700	茵 .	6,	U
	ALL PREVIOUS W	ITNESSES WERE REN	NOVED DI	JRING NEW ROAD CONSTRI	UCTION.	lo m I	工	3	반
	THE DUAT MONITH	MENT TO THE EAST V	VAS NOT	FOUND. THE CORNER APP	PEARS TO BE IN	这声号		À	3
		LAT LINE TO THE EAS		TOOMS. THE GOTTIER AT	EARO TO DE III	N-E	3	2	7
			•			222	É	3	面
	VERIFIED 1989 EI	DISON MEASUREMEN	T TO K-3 (R=2593.71, M=2593.72)		ストだ	e j	_ >	H
	AND TO K-5 (R=2:	356.83, M=2356.71)				RH	8.	\searrow	P.
						歪びび	707	1	7
						になる		3	3
						102	~~	18	M
						区。	\sim	CV.	31
^	Deposite of	ant for corner and sees	seenrine o	stablished to perpetuate loca	iting the position of		5/		E
C.						LEE		i	<u>'</u>
		DUNTY REMONUMENT	ATION MA	ARKER AND CAP #25826 IN E	EXIST. MON BOX.		Sa.	Minda.	- [
	WITNESSES	-D FIDE LIVEDANT 114	0141 00 04			E ST	<u>~</u> _1	10	% .
	TOP CENTE	ER FIRE HYDRANT, N4	∠VV, 89.64 : 34	•	á	村之之	7	***	4
		T N SIDE PP, S88E, 66 T N SIDE PP, N85W, 6			<i>3</i>	KXXX	BRUCE	1	* 1
			v.v		₹		STULIFIE	•	. "
	NW COR O	C.B. @ BACK/CURB, S1	2W, 43.75		~	Mario A	DUENCH		* 1

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

_ Date 12-9-93

25826

CHAI GIAND