

LIBER 061660044

B999657

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Macomb
 (County)

Located In:
Shelby Twp.

Corner Code #

RECORDED IN MACOMB COUNTY
 RECORDS AT: 8:30 A.M.

DEC 28 1993

1. Public Land Survey T 3 N R 12 E L-3
 T _____ R _____
 T _____ R _____
 T _____ R _____
 T _____ R _____
2. Property Controlling in Section S _____ T _____ R _____
 S _____ T _____ R _____
 S _____ T _____ R _____
3. Miscellaneous Property in Sec. S _____ T _____ R _____
 S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Lamelle Hough
 CLERK - REGISTER OF DEEDS
 MACOMB COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

I, Huston K. Kennedy, in a field survey on December 14, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S.: Set Post; 14" Elm S51°W 10 Lns; 8" Ash S80°E 3 Lns
 1979-Kobs, P.S. #14097; LCRC L.3186, Pg.877 - Fnd 1/2" Iron Rod in monument box
 1979-Kobs, P.S. #14097; Survey L.3186, Pg.895 - Same wits as 1979 LCRC
 1986-King, P.S. #30085; Survey L.4077, Pg.562 - Same wits as 1979 LCRC
 1989-King, P.S. #30085; Survey L.4621, Pg.463 - Same wits as 1979 LCRC
 1990-Kobs, P.S. #14097; Survey L.4866, Pg.818 - Same wits as 1979 LCRC

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod in a monument box located 2.5' North of the centerline of 25 Mile Road, which is bituminous surface. There is a tree line extending to the North and a tree line extending to the South that is 10'± West of the section corner.

All witnesses from the first LCRC above are existing and they were used to recover and verify the location of the found 1/2" Iron Rod in a monument box.

ACCEPTED BY THE MACOMB COUNTY
 SURVEY PEER GROUP AS THE OFFICIAL
 CORNER UNDER MICHIGAN PUBLIC ACT 345
 OF 1990 AT A MEETING HELD ON
12-20-93
Frank J. DeDecker
 FRANK J. DeDECKER, PS, PE, CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3 I replaced the found 1/2" Iron Rod in a monument box with 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a monument box.
 S40°W-101.70'-Set PK & Remon. tag NW face Power Pole
 N16°E-24.28'-Set PK & Remon. tag West face Power Pole
 N50°E-118.75'-SE corner of house #14399
 S72°E-41.25'-Set PK & Remon. tag North face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by H K Kennedy
 Surveyor's Michigan License No. 17623

Date 12/14/93