

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Macomb
(County)

Located In: Corner Code #
Lenox Township

SURVEY &
REMONUMENTATION

FEB 27 1997

COMMISSION

1. Public Land Survey T 4N R 14E A4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, Craig P. Amey, in a field survey on June 15, 1996 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1817 William Preston Set post GLO

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found pipe at the base of an old fence corner. Old fences running north, south and east. The pipe is also at the SE top of bank of drainage ditches running east and south. The location is supported by the construction documents for the drain, currently on file at the Macomb County Drain Commission. No other recorded or occupation evidence exists.

North 2728.79' Northwest corner of section 7 (A3) 40 chains or 2640' GLO, 2707.28 prorated
South 2685.78' Southwest corner of section 7 (A5) 40 chains or 2640' GLO, 2707.28 prorated

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 3/4" by 24" rebar with a 2" diameter aluminum cap stamped "Macomb County Monument MI ACT 345 A4 34970" 0.93' W of the pipe on the township line.

21°	19.80'	Set PK and MCR tag in the E face of a 22" Swamp Oak
125°	157.84'	Set 1/2" rebar with "TRAV" cap
230°	24.55'	Set PK and MCR tag in the SE face of a 5" Ash
195°	36.78'	Set PK and MCR tag in the E face of a 15" Elm
180°	106.47'	Set a 3/4" by 24" rebar with a 2" diameter aluminum (M4, T4N, R13E)

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
AS THE OFFICIAL CORNER UNDER MICHIGAN
ACT 345 OF 1990 AT A MEETING HELD
ON 10-22-96
William E. Soderberg
WILLIAM E. SODERBERG, P.S., CHAIRMAN



Signed by Craig P. Amey Date November 30, 1996

Surveyor's Michigan License No. 34970

605