

MAY 16 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Mansitee
(County)

Located In:

Corner Code #

1. Public Land Survey	T	21N	R	15W	D-11
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous	S		T	R	
Property in Section	S		T	R	

REGISTER'S OFFICE
MANISTEE COUNTY

96-163 at 1:05pm
MAY 15 1996

Deborah Six
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Richard L. Hays, in a field survey on April, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-11 QUARTER CORNER COMMON TO SECTIONS 29 & 32

1837:G.L.O. Set Post

10" Y. Pine S-41°-E 48 Lks(1)

9" Y. Pine N-81°-W 83 Lks(2)

1908:D. Skeels Book B, Pg 272,273

10" W. O. N-24°-W 71 Lks(3)

30" P. S. S-41°-E 48 Lks(4)

1975:Carl Roser #12028 L.C.R.C. 77-13

Section 32 Survey, Fd. 1" pipe from

Walker Survey in 1949 and added

D.N.R. Monument

3" W. Pine N-42°-W 47.0' (5)

6" Oak N-75°-E 12.6' (6)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-11 QUARTER CORNER COMMON TO SECTIONS 29 & 32

1996:Found D.N.R. Monument. Condition of the Recorded Witnesses are
as follows

10" Y. Pine S-41°-E 48 Lks(1) GONE

9" Y. Pine N-81°-W 83 Lks(2) GONE

10" W. O. N-24°-W 71 Lks(3) GONE

30" P. S. S-41°-E 48 Lks(4) GONE

3" W. Pine N-42°-W 47.0' (5) GOOD

6" Oak N-75°-E 12.6' (6) GOOD

ratified by the Manistee County Peer Group
according to the county plan adopted pursuant to P.A. 345 of 1990,
as amended, (being the State Survey and Re-monument Act, MCL 54.261
et seq.). Date of Peer Review: MAY 10 7 1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11 QUARTER CORNER COMMON TO SECTIONS 29 & 32

1996:Accepted D.N.R. Monument as the best available evidence of the
position of the Original Corner.

7" W. Oak N-76°-E 12.93'

22" B. Oak S-62°-E 20.19'

6" W. Pine N-42°-W 47.24'

13" B. Oak S-88°-W 27.10'

Signed by

Richard L. Hays

RICHARD
L. HAYS
LAND
SURVEYOR

Date

May 7 1996

Surveyor's Michigan License No. 25847

NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971