

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Manistee Located In Corner Code #
(County)

- 1. Public Land Survey T 23N R 14W G2
2. Property Controlling in Section S T R
3. Miscellaneous Property in Section S T R

4. Lot No: Recorded Plat:
5. Private Claims:

I, Craig W. McVean, in a field survey on July 8, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Cell G3 contains a black dot representing a corner point.

A. Description of original monument and accessories and/or subsequent restoration:

- G2 - 1839 - GLO - Set 1/4 Post - H. Bervort, Jr.
1) Beech 10" N33°W 12 L.
2) Beech 10" S46°W 28 L.
- 1914 - CSR - L. 'A', p. 194 & 195 - E. W. Muenscher
Found remains of Beech BT; 3) Cherry 5" S44°W 48 L.
- 1972 - LCRC #73-9, C. F. Roser - Recovered corner per J. H. Millard. Fd. 1 1/4" pipe buried 0.5'; 4) 5" R. Pine S40°W 38.4'; 5) 4" R. Pine N27°W 48.2'
- 1989 - Rec. Survey L. 2, p. 83 - 88 - J. E. McLane; Fd. 1 1/4" pipe in E'ly edge of 'Y' trail intercept at 18' S'ly of W. Bound 2-Track; 4) Fd. Spike in 10" Red pipe Az 220° - 38.44'; 5) Fd. Spike in 7" R. Pine Az 333° - 48.33'; 6) Set nail/tag SE side 8" Jack pine Az -52° - 42.68; 7) Set nail/tag SW wide 6" J. Pine Az -138° - 45.80

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- G2 - 1/4 Corner Common to Section 3 & 4 - Fd. 1 1/4" I. D. x 25" long iron pipe per Roser and McLane. Witnesses #1 through 3 are gone. Pipe in line with overgrown 2-track to East. 2'± W. of N-S 2-track and 21'± South of centerline 2-Track West. This pipe fits well with occupation and road lines N, S, E & W and is accepted as Muenscher's careful & faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G2 - Replaced 1 1/4" x 25" long iron pipe with stamped 4" DNR Alum. Cap on 1" x 36" galv. iron pipe encased with 4" x 12" PVC pipe with concrete around cap. Buried 0.8'. Set Blue Carsonite Post with loc. Tag 33' West. N48°E 42.62' to set N & T at fd. N & T in SE side 10" J. Pine (#6) N31°W 48.28' to fd. Nail in W. side 12" R. Pine (#5) S36°W 38.44' to set N & T at Fd. Nail in W. side 13" R. Pine (#4) S58°E 44.36' to set N & T in NE side 3" Cherry



Signed by: [Signature]
Surveyor's Michigan License No.: 39088

Date: 12/10/2009