

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Manistee
(County)
Located In
Corner Code #

- 1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

I, Craig W. McVean, in a field survey on July 15, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains a grid of numbers 1-36 and a central black dot at the intersection of G and H.

A. Description of original monument and accessories and/or subsequent restoration:

- G5 - 1839 - GLO - Set Post - H. Brevort, Jr.
1) Tamarack 12" N15°W 8 L.
2) Tamarack 8" N6°E 7 L.
- 1900 - CSR - L. 'A', p. 194, 200, 201 & L. 'B', p. 14 & 15 - J. H. Millard - Gov't corner very plain. Tam. with Plain marks stands.
3) Tam. 6" S3°E 14 L. 4) Cedar 12" S15°E 52 L.; 5) Tam. 12" N 33½°W 18 L.
- 1923 - CSR - L. 'B', p. 344 & 345 - T. Norlin - Iron pipe
6) Cherry Stp. 20" N. 5'
- 1968 - Consumers Power Co. Drawing #S-F 16874, Sheet 38. Distance North 2670.00'; Distance West 2542.00'.
- 1979 - Rec. Sur. L. 1, p. 602 A - J. L. Wilcox - Fd. 2" pipe; 7) N60°W 15.05' - 8" B. Ash;
8) S30°E 5.98' - 10" B. Ash;
9) S10°E 29.37' - 18" Y. Birch;
10) S42°W 27.88' - 16" Cedar

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- G5 - Sec. Corner common to Sec. 9, 10, 15 & 16 - Fd. 2" O. D. iron pipe in Cedar swamp. Witnesses #1 through #6 are gone. #7 - OK; #8 - Fd. Stp; #9 - Dead snag; and #10 - Fallen. Measured grid bearing & distance of N2°50'16" E 2668.96' (2640' - GLO, 2669.7' - JHM, 2670.0' - TN, 2670.0' - CPC, 2668.6' - JLW) to 'G4'. 2" iron pipe accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G5 - Drove stamped 2" Aluminum Cap on 5/8" x 34" rebar into found 2" O.D. iron pipe. Set Blue Carsonite Post 1' SE
S11°W 20.14' to set N & T in W. side 10" Ash - Fd. Blazed
N41°W 5.13' to Fd. Nail in NE side 9" Cedar
North 27.38' to set N & T in W. side 22" R. Maple
S71°E 26.40' to fd. Nail in S. side 14" Cedar
S52°W 36.87' to set N & T in SE side 9" Cedar
N60°W 15.06' to Fd. nail in N. side 10" B. Ash (#7)



Signed by: [Signature]
Surveyor's Michigan License No.: 39088

Date: 12/10/2009