

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Manistee

(County)

Located In

Corner Code #

| | | | | |
|--------------------------------------|---|---|---|-------------|
| 1. Public Land Survey | T | | R | |
| | T | | R | |
| 2. Property Controlling in Section | S | 1 | T | 24N R 14W 7 |
| | S | 1 | T | 24N R 14W 9 |
| 3. Miscellaneous Property in Section | S | | T | R |
| | S | | T | R |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on May 17, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

7 - 1901 - CSR - L. A, p. 264 & L. B, P. 68 - Set Cedar stake
1) Tel. p. 9 S18°E 122; 2) Do. N86°W 47 - N19°E 120.

9 - 1901 - CSR L. 'B', p. 68 and L. 'A', p. 264 - J. H. Millard
1) Sugar 20" S49°W 18½;
2) Sugar 22" N30°E 44 ½
- 2003 - Unrec. Survey - R. M. Harris File #03-5072 - Set Rod & Cap.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

7 - N 1/16 Corner common to Sec. 1, T24N, R14W and Sec. 6, T24N, R13W - No conclusive evidence of Millard position or BT's. Set 2" Alum. Cap on 5/8" x 22" rebar per standard BLM procedure. 7' West of Phy. Centerline N-S Bit. Rd. Down fence remains to West are 8'± South.

9 - CE 1/16 Corner Sec. 1 - Fd. ½" capped iron #25845 in line with Fence remains W. and on west edge of field furrow south. Dug for evidence of Millard position in dry sand but nothing conclusive was found. The BT's are gone. ½" CIR accepted as the best available evidence of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

7 - Stamped 2" Alum. Cap on 5/8" x 22" rebar
West 33.00' to set 2" Alum. Cap on 5/8" x 34" rebar on line with Blue Carsonite Post with loc. tag.
N33°W 58.48' to set N & T in SW side 15" R. Pine
N58°E 74.63' to set N & T in NW side 10" R. Pine
S48°E 114.50' to set N & T in NW side 13" R. Pine

9 - Replaced ½" CIR #25845 with stamped 2" Alum. Cap on 5/8" x 34" rebar
N50°W 54.36' to set N & T in SW side 11" R. Pine
N6°E 64.56' to set N & T in W. side 15" Cherry in Clump - 5
N78°E 115.39' to set N & T in N. side 12" R. Pine
SW 0.35' to face of 3" x 6' Tall PVC pipe
Set Blue Carsonite Post with loc. tag 1' N.
S46°E 39.22' to set N & T in SW side 26" Cherry

Signed by:

Craig W. McVean

Surveyor's Michigan License No.: 39088

Date:

5/18/2012

