SURVEY & REMONUMENTATION

MAR 1 6 1998

LAND CORNER RECORDATION CERTIFICATE

| SECTI | ON | Filing Requirement of Act 74, Mich. P.A: 1 | | | | 1111.5 | j) | | | 1 |
|---|---|--|--|--|--|-------------------------------|---------------------------------------|--------------------------|-------------------------|---|
| For corners in MASON (County) | Locate | ed In: | Corner Code # | 12: | 52 | | | · | P.M | |
| Public Land Survey Property Controlling in Section | T 171 T T T S T S T | N R 16W R R R R | U -05 | | | SHILL STER (| OUNT) | noKl Y | | |
| Miscellaneous Property in Sec. | S T | T R Register of Deeds Stamp & File Nu | | | | | | | | er |
| 4. Lot No. 5. Private Claims | Recorded Plat | | | 1 | A B | СЪ | E F G | > H ∣ | ΙJΚ | L |
| | | | | 2 | 1 ' | 5 | 4 | 3 | 2 | 1 |
| i. Kenneth L. Ross , in a field survey on November 5, 19 97 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land | | | | | 7 | 8 | Ŷ | 10 4 | 11 | 12 |
| above were in conformance Court of Law; established | ora Courtoftaw and with the rules of the | d/or that the corner po | torthe Interior, Bureau of Lar ints mentioned in lines 3, 4 and and Surveyors or by a Decree of umented, recovered, found a | 15 7 | 18 | 17 20 | 16 21 | 15 | 23 | 13 |
| NOTE: Not more than | 4 corners, all in t | | d range, may be recorded | 9 | | 29 | 28 | 27 | 26 | 24 25 |
| on mis certific | ate. | ÷ | r subsequent restoration: | 11 12 | 31 | 32 | 33 | 34 | 35 | 36 |
| | | accessories $a_{RQ/0}$ and 15, $T17N-R16$ | | 13 | | | 1. | | | |
| Set Wood Pos #1 Beech 8" #2 Beech 7" | N 57°W 14 lks S 63°E 16 lks Metcalf Stake and witnes | s. (9.24 ft.) s. (10.56 ft.) ss stumps | 1972, J. Borsfay, MC 1/2" x 48" iron pipe Set Monument box #3 Poplar 4" NW 75.0 #4 Tw. Oak 15"-24" NE 52.68' #5 Cherry 4" NE 52.9 | Fou 199 | 3, Ken nd Iro 0, Gor nd Iro | n in H don Bo | onumen nnev. | t Box | 12016 | |
| | | | ied in restoring or reestabli | shing corner | : | | | | | |
| | | d 15, T17N-R16W | | | | | | | | |
| Iron Pipe, 36" long, in dispute this location | side an existing for the corner | Renneth Ross and g monument box, . Note : Old | Kevin Pritchard(surve at the center-line of fence line running to | y tech) for Hawley Road the South | ind a 3 (paved | 3/4" Ix 1). I | on Pir found | ne and no ev | a 1/2 idence | ?" to |
| Conditi | on of recorded | witnesses are; und in good cond | #1 Gone #2 Gone | #3 Found i | n good | l condi | tion | | | |
| | | | | | | | | | | |
| C. Description of monun | nent for corner and | d accessories estat | olished to perpetuate locati | na tha wasti | 64 | | | | | |
| H-05 1/4 Corner for | sections 10 an | d 15, T17N-R16W | mental to perpetuate locati | ng the position | on or th | e corne | r: | | | |
| I replaced Honument (5/8" re-rod, a existing monument box. corner. | i, in the exact 24" long, with a And is accepted | location, the 3/ 2 1/2" aluminum as a careful an | 4" Iron Pipe and 1/2" or cap, stamped to ident and faithful re-establis | Iron Pipe, ify the con hment of th | with a mer. F me posi | s stand Re-rod (tion, c | lard Ha was pl | ason C laced origi | lounty inside hal | Α. |
| Ext. "BT" #4 Tw. Red Ext. "BT" Black Oak Cherry 6" Jack Pine | 8" \$ 01° E N 35° W | 46.63 ft. (Set 6 | 75 ft.(Ext. 16p in SE : Ext. 60d spike in East Od spike in SW side of 10p nail in SW side of | side of tr | ee) (1/2711111111111111111111111111111111111 | 10000H2 | E E E E E E E E E E E E E E E E E E E | 10 | | 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - |
| Signed by | Alfor |) | Data // | , e' | | | 1 7 5 | 3 4 | | . |
| Surveyor's Michigan Linea | | | Date Lo | 1. 2./ | 77/ | 17. | ED 11 | 1 8.0% | <i>is</i> , | |

LIBER 4 PAGE 135