## SURVEY & REMONUMENTATION

	APR 2 8 199	5										·	
COMMISSION For corners in		ION	LAND CORNER RECORDATION CERTIFICATE			FILED							
		!ON	Filing Requirement of Act 74, Mich. P.A. 1970		.A. 1970	AT	7	35	O'CI	ock.		ρ	1
FOI (				0		<b> </b> ^'' -						1	
	MASON (Sounty)	Loca	ated In:	Corner Code ##		1		N.	<b>OV</b> 2	2 100	λA		
1. F	Public Land Survey	T _ T _	18N R 18W — R — R — R — R	L-1				MARY	GOLD ASON	EN KOUN	)LAS		
2. F	Property Controlling	S T _	R	<del></del>		_		11LC	IO LI	0, 0			
į	n Section		R										
3. 1	Miscellaneous		R		Regi	ster	of D	eeds S	tamp	& File	Num	ber	
F	Property in Sec.	S T _	R				<u> </u>						
<i>1</i> 1	ot No	Recorded Plat					_						,
						Â	В	C D	E F	G Н	<del>                                     </del>		L M
		-	•			2	6	<u> </u>	<u> </u>	- 3 -	┼─ <sup>╆</sup>	+	-
						3	+	+	+	<del></del>	+	+	+
ф	baadana II. Wainart		ለረፕ	יייי פעמען	Q.A.	4	∤—	— ģ —	<u> </u>	10	<del> </del> -11		12
l,	heodore H. Weinert	_ , in a field sur	vey on001	OBER , 19, 19, A. of 1970, the corner points menti		5		-	$\vdash$		+	-	+-
in lin	ereby centify that under r les 1 and 2 above were	in conformance	with regulations	and rules therefore as required i	in the	6	18	—1 <sup>7</sup> —	—1 <sup>'</sup> 6	15—	<del> </del> -14		₁(3
curre	ent manual of survey ins	tructions of the U	nited States Dep	artment of the Interior, Bureau of	Land	7	+	-		╂-┼-	╂╌╂	+	+-
				ner points mentioned in lines 3, 4 d of Land Surveyors or by a Decre		8	19—	20	21	22	-23		24
Cour	t of Law; established,	re-established,	monumented, re	e-monumented, recovered, four	nd as	9	+	$\vdash$			+-+	-	+-
expr	essed below:					10	30-	29	-28-	27-	26	+	·25
NOT		-	he same town	and range, may be recorded		11	╁		$\vdash\vdash$	<del>                                     </del>	+	+	+-
	on this certificat	e.				12	·3/1	32	33-	34-	-35	+	36—
	Description of origina 1 1/4 Corner, Sec Corner not set do December, 1894, Mitchell tied in found (Book 1, P	. 1 uring original and April 7 & to corner with	government s 8, 1895, J. A out stating w	rhat was	<b>1</b> :	13 L	<del>-  </del>	<u> </u>		I [	1		<b>_</b>
	Description of corner 1 1/4 Corner, Sec Pound 1" Pipe ID S 1/4 Sec. 36, T Matched distance	. 1 at corner loc 19N, R18W, 4.5	ation. 8' West.	d applied in restoring or reest	tablishing (	corne	er:					•	

within 1.83' long from the west and 8.35' long from the east. This corner location is accepted as a careful and faithful perpetuation of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-1 1/4 Corner, Sec. 1 Set 5/8 % X 24 " rebar inside 1 " ID pipe as found with standard 2 1/2" cap stamped "Mason County Remonumentation". 8" Maple N 72 E 47.61' 12" Maple S 37 E 33.70' 18" Maple S 43 W 22.92' On CL Decker Road S 1/4 Corner Section 36, T19N, R18W, West 4.58'

Date

Signed by Murun Surveyor's Michigan License No. 19846

тиворова на

និយន់ ន

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983

Peer Group Reviewed and Approved Kenneth L. Ross

LIBER

3PAGE 235