

Land Corner Recordation Certificate
Attachment B to 2018 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2018 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2018 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland Co.

Porter Twp.

Corner Type	Survey Township	Corner Code
Original Public Land Survey Corner	T 13N R 1W	C5
• MCL 54.202(g)	T R	
• MCL 54.262(g)	T R	
Property Controlling Corner	S T R	
• MCL 54.202(l)	S T R	
• MCL 54.262(h)	S T R	
Protracted Public Land Survey Corner	T R	
• MCL 54.202(k)	T R	
• MCL 54.262(i)	T R	

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2	6		5		4		3		2		1			2
3														3
4	7		8		9		10		11		12			4
5														5
6	18		17		16		15		14		13			6
7														7
8	19		20		21		22		23		24			8
9														9
10	30		29		28		27		26		25			10
11														11
12	31		32		33		34		35		36			12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

C5 – Corner common to Sections 7, 8, 17 & 18, T13N, R1W –

- 1852 –GLO Resurvey- A. Burt – Set post.

1) Elm 14" S15°E 27 L.; 2) B. Ash 12" N43°W 39 L.

- 1900 – CSR - P. 68-71 – F. T. Gibbs – Petition Survey in sections 17 & 18.

Set new post in place of old one.

- No date – CSR FB. P. 13 – iron bar and stone

- 1934 – Joe Harrod – Sleigh shoe on S. side large stone (on N. side of ditch)

- 1983 – LCRC # 591 – T. J. Mueller (PS # 25861) – Found sleigh shoe south side of two stones [± 15' N. of fence west. 6' West of fence to North]

3) N65°W 41.04' – 20" Oak; 4) N30°W 30.43' – 12" Maple; 5) N25°E 14.75' – 12" Ash; 6) N70°E 38.69' – 6" Oak

- 1995 – Ledy & Assoc. notes – set ½" rod w/ cap @ int. of fence cor.

7) East 29.73' to nail in 36" tree

8) NW 12.80' to nail in 50" tree

9) North 27.30' to nail in 10" aspen

- 1996 – Rec. Survey L. 5, p. 419 – J. S. Fokens (PS # 21567) – Fnd. Fence Corner; Same witnesses as LCRC # 591.

- 2005 – Rec. Survey L. 6, p. 941 – T. E. Bebee (PS # 39074) – Fnd. Sleigh Shoe

- 2008 – Rec. Survey L. 7, p. 297 – J. H. Rauser (PS # 39096) – Found Sleigh Shoe

4) N30°W 30.60' Fnd. Nail 12" Maple; 5) N25°E 14.75' Fnd. Nail 12" Ash; 6) N70°E 38.89' Fnd. Nail 10" Oak;

3) N65°W 41.20' Fnd. Nail 18" Oak

- 2015 – Rec. Survey L. 7, p. 649 – T. E. Bebee (PS # 39074) – Shows corner

- 2015 – Rec. Survey L. 7, p. 670 – J. H. Rauser (PS # 39096) – Shows corner –

Fnd. Sleigh Shoe, S. side of 2 stones

3) N65°W 41.04' – 20" Oak Stump. Wits 4 to 5 same as L. 7, p. 297; 6) N70°E 38.69' – 6" Oak Stump

Professional Surveyor's License No.: 26454