

SURVEY & REMONUMENTATION

FEB 23 2001

SECTION

APPROVED LAND CORNER

P.A. 345 OF 1990 LAND CORNER RECORDATION CERTIFICATE
MIDLAND COUNTY Filing Requirement of Act 74, Mich. P.A. 1970
Midland County Remonumentation

494

8/24/00 JRF

For Corners in

Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 13N R. 1W H-11

T. R.

T. R.

2. Public Controlling

S. T. R.

in Section

S. T. R.

3. Miscellaneous

S. T. R.

Property in Section

S. T. R.

4. Lot No.

, Recorded Plat

5. Private Claims

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 6, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11				*									
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt
40.24 1/4 Cor 80.54 Sec. Corner
Hemlock 14" S10°W, 12 LINKS
Hemlock 7" N15°E, 20 LINKS

1901, Gibbs
Same as 1902 Survey

1902, Gibbs
Stone with iron under set at
avg. dist on true line.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" x 6" pipe in Mon. Box 6 1/2' South of C.L. of new asphalt pvm't. Excavated to 1.0' and hit large flat stone. Measured West 2651.51 to G-11 and East 2651.34 to I-11. Corner is on line between G-11 and H-11. Accepted 1/2" pipe as best available evidence of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 10" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458" in Mon. Box.

Witnesses:

N60°E, 63.30' - N & T in P.P.
S60°E, 75.23' - N & T in Guy Pole
S10°E, 35.71' - N & T in 8" Pine
N10°W, 42.61' - Top Cen. 15" C.M.P.



Signed by Mark R. Robison

Date 9-15-2000

Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

REVISED MAY 14, 197
REVISED JAN., 198