## **APPROVED LAND CORNER** P.A. 345 OF 1990 **MIDLAND COUNTY**

## REMON. COR. H-7 INGERSOLL TOWNSHIP

12/05/94 950		RECORDATION CEI		yw see	
For corners in	ring nequirer	ment of Act 74, Mich.	r.A. 1970		
Midland	•			194	
(County)	Located in:	Corner Code #			
1. Public Land Survey	T 13N R 2E	H-7	ar <b>*</b>	STATE OF HICHIGAN	
Ti Tubilo Luilo Gui Voy	TR			NIDLAND COUNTY	
• •	T R			REMONUMENTATION & FILED	
A. Branchi Canturillina	TR	<del></del>		10 JAN 95 3:11 P.H.	
2. Property Controlling S_ in Section S	— T — R —			TA ALLE LA D.TW. SILE	
3. Miscellaneous S	_ i _ R			BEVERLY J THAYER	
Property in Sec. S	T R_		Register of Deed	s Staffip & File Wurnber	
4. Lot No, Recorded Plat			* 5 0	DEFGHIJI	7 T M
5. Private Claims			ABC	DERGUIDI	/ Ti Ii
I, RODNEY CLAYPOOL, in a field survey on O	ct. 26, 19 94, do hereby	certify	2 -6	5432-	-i
that under requirements of P.A. 74, Michigan	•		3	<del>┞╸┞╸┞╸┠╸╏</del> ╶╃╶┥	
lines 1 and 2 above were in conformance with	-	•	4 7	891011-	12
in the current manual of survey instructions			5 18-	17-16-15-14	-13-
Interior, Bureau of Land Management or by a corner points mentioned in lines 3, 4 and 5 an	· ·	•	6 -18 -	17+-10+-13+-14-	
of the Michigan Board of Land Surveyors or b				20 - 21 - 22 - 23	_24-
monumented, re-monumented, recovered, for	•		9	<del>                                      </del>	
				29-28-27-26	<u></u> —25-
NOTE: Not more than 4 corners, al		and range, may be	11	<del>                                      </del>	
recorded on this certificate.	•		12 -31-	32+-33+-34+-35-	<del>-36-</del>
A. Description of original monument	and accessories and	d/or subsequent resto	ration:	10 1	
H-7 Corner common to Sections 15 and 22				RODNEY	
Government survey 1830's, set woo	d post			CLAYPOO LAND SURVEYOR	L ) #
Survey by J. Jones, 1989, set PK na	iil at rec. distance from G	i-7 and rec. angle to G-8		No.	15
LCRC D. Whittier, 1972, 1/2" rod wit	th T-bar on E side			29241 (AND 5)	
WITNESS NOTE: Witnesses from aboresented to peer		RC's are available in do nd is on file at the Regi			
B. Description of corner evidence for	und and/or method	applied in restoring or	reestablishing co	orner:	
H-7 Corner common to Sections 15 and 22					
Found PK nail set 3/4" pipe and bra	ass cap, per survey by J.	Jones and LCRC by D. Whi	ittier.		
Corner <u> </u>			- <u></u>		ي19 ,
C. Description of monument for corn	ier and accessories	established to perpetu	ate locating the p	position of the corner:	
H-7 Corner common to Sections 15 and 22					
Set 3/4" pipe and brass cap stampe as the best available evidence of th			per survey by J. Jon	es and LCRC by D. Whittier a	nd is ac
S 5 Deg W, 19.32', notch in south e North, 40.96', notch in north end 36 N 40 Deg W, 75.48, centerling too to	6" C.M.P.	_	0.42', nail and plastic rge conc. mon with t	• •	

Date \_

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 197 Revised May 14, 197

Revised Jan., 1983