APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

6/6/9	25	200
For corners in		0

expressed below:

LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in	Filing Requi	irement of Act 74, Mich. P	A. 1970 COMMISSION
	MIDLAND	Located In:	Corner Code ##	217
	(County)			Mil
1.	Public Land Survey	T 13N R 2W	G-7	
	•	T R	1	STATE OF MICHIGAN
	•	T R		KIDLAND COUNTY
		T R		FILED
2.	Property Controlling	S _ T R		
	in Section	S T R	·	19 JUL 95 10:52 A.M.
3.	Miscellaneous	S T R		Register of Boods Stemp & Fits Number
	Property in Sec.	S T R		Register of Deeds Stamp & File Number
		1		REGISTER OF DEEDS
4.	Lot No,	Recorded Plat		- A B C D E F G H I J K L
5.	Private Claims			
				2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
				3
		•		4 - 7 - 8 - 9 - 10 - 11 - 12-
Ι, _	PAUL B. LAPHAM	_ in a field survey onMAY	, ₁₉ <u>95</u>	. 5
do	hereby certify that under re	equirements of P.A. 74, Michigan P.	A. of 1970, the corner points menti	oned

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration: G-7 CORNER COMMON TO SECTIONS 15, 16, 21 & 22

1852 AUSTIN BURT, POST, OLD CORNER, Y. BIRCH 10" S83 1/2"W, 25 1/2 LKS., B. ASH 12" N68"E, 46 LKS.

10-18-73 JEROME SCHAFER, FOUND 3/4" PIPE IN MON. BOX

10-9-74 DAVID WHITTIER, 3/4" PIPE IN MON. BOX

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-7 CORNER COMMON TO SECTIONS 15, 16, 21 & 22

FOUND CAPPED IRON (P.S. NOS. 17741 & 24625- GRAY & WOOD) AT INTERSECTION OF CENTER LINE OF ASPHALT ROAD EAST-WEST AND SEAL COAT ROAD SOUTH. MEASURED WEST 2659.02' TO F-7 (CSR 2649.60) MEASURED SOUTH 5286.16 (CSR. 5291.22) TO G-9. MEASURED EAST 2648.04 TO H-7. AFTER PEER REVIEW, ACCEPTED CAPPED IRON AS PROPER POSITION OF THE CORNER. FOUND P.P. S45°E, 66.42 FEET, PER SURVEYS BY SCHAFER AND WHITTIER.

Corner, G-7 was approved for remonumentation at a Peer Review Committee Meeting on 6-6 , 19<u>95</u>. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-7 Corner common to Sections 15, 16, 21 & 22
Set 5/8" x 18" re-rad with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box. Accepted as best available evidence of the accepted position of the corner.
N45"W, 53.40' - NAIL & TAG IN T.P. PHONE RISER.
S45"W, 67.9' - NAIL & TAG IN P.P.
S45"E, 66.42' - NAIL & TAG IN P.P. (OLD WITNESS).
N45"E, 36.04' - NORTH END OF CULVERT.

CF W FAUL 8. LAPHAM PROFFESIONAL SURVEYOR 20. 9433 Service ! O STATE OF THE PARTY OF THE PAR

Surveyor's Michigan License No.

_ Date _

12