

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

SURVEY &
REMONUMENTATION

FEB 24 1998

MIDLAND COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE SECTION
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MIDLAND
(County)

Located In:

Corner Code #

1. Public Land Survey

T 14N R 2W A-7
T R
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat
5. Private Claims

I, MARK R. ROBISON, in a field survey on July 1, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1830 Burt
Post 105 lks North of Std. Cor
8-3-76 Kattouah (132) 2-194
Wit.-S75W 48.5 Street sign
N55E 49.0 - 18" Tree
South 2608.59 to A-8 (See Rec. Dwg)

10-3-86 Ankrom L.C.R.C.# 620
Set C.I. at G.L.O. falling from Std. Cor.
Wit.-S42W 53.20 Tele. Box
N53E 43.26 3" Maple
N45W 83.30 3" Maple
South 69.30, NE Cor, Sec 24, T14N, R3W

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 12" C.I. Excavated and found no other evidence. Got magnetic reaction at hole in asphalt at Standard Corner. Found all 1986 witnesses. Measured South 2642.14 to A-8. (Measured 2640.98 after A-8 was revised to fit GLO falling.)

Corner, A-7 was approved for remonumentation at a Peer Review Committee Meeting on Aug. 1, 1997.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" Gas Pipe with Brass cap stamped "Midland Co. Remon. Cor. P.S. 27458" in Monument Box. Accepted as best available evidence of accepted position of corner.

Witnesses:

S42W 53.14 Center of Tele. Box (OBT)
N50E 43.26, nail & tag, 8" Maple (OBT)
West 32.18, nail & tag, P.P.
South 69.30 NE Corner, Section 24, T14N, R3W (OBT)

Signed by Mark R. Robison
Surveyor's Michigan License No. 27458

Date 10-31-97

