

REMON. COR. D-7, LARKIN TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Midland

(County)

Located in:

Corner Code #

1. Public Land Survey

T 15N R 2E D-7
T R
T R
T R

2. Property Controlling
in Section

S T R SURVEY &

3. Miscellaneous
Property in Sec.

S T R REMONUMENTATION

FEB 28 2001

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____ SECTION _____

I, RODNEY CLAYPOOL, in a field survey on August 4, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-7 ¼ Corner common to Sections 17 and 20

Survey by Glo, 1830's, set post
Survey by D. Whittier, 1963, 1971, found
Survey by M. Hunter, 1966, set railroad spike
Survey by D. Ledy, 1994, found
Survey by J. Jones, 1994, 1996, 1998, found ¾" pipe
LCRC by P. Lapham, 1983, ½" pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-7 ¼ Corner common to Sections 17 and 20

Found ½" rod and cap 2' long per surveys by D. Whittier, M. Hunter, D. Ledy, J. Jones and LCRC by P. Lapham.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7 ¼ Corner common to Sections 17 and 20

Replaced rod with 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

S 15 Deg W, 47.35, nail and tag in power pole, Rec. 47.37
S 15 Deg E, 97.60, Northwest corner barn, Rec. 98.3
N 5 Deg W, 34.58, nail and plastic disc in power pole, Rec. 34.44
N 40 Deg E, 69.40, centerline 2" Maple
S 82 Deg W, 209.50, centerline top fire hydrant

Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983


512

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
Register of Deeds

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



APPROVED LAND CORNER
P.A. 345 OF 1980
MIDLAND COUNTY

12/27/00