

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

- Notes:
• No more than two Original Public Land Survey Corners can be recorded on this certificate
• If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
• If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville Twp.

Form with columns: Corner Type, Survey Township, Corner Code, and a grid of 13 rows and 13 columns (A-M) for recording corner data.

Part A: Corner(s) History

- C9 – 1832 – Set Post – H. Parke
1) Pine 10" S54°W 15 L.
2) Pine 10" N44°E 4 L.
- 1852 – GLO Dependent Resurvey – A. Burt – Old Corner
3) Beech 7" S83°E 16 L.
4) W. Pine 20" N60°W 14½
- 1901 – CSR L. 1, p. 92 – F. J. Gibbs
Set Post. Stump of old bearing standing.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

C9 – Section Corner common to Sections 19, 20, 29 & 30, T16N, R1W – Dug 3± diameter hole from the apparent remains of witness #4. Fd. Vague vertical discoloration that fits record bearing and distance from 20"± White Pine stump remains. From this position retraced GLO resurvey line North as follows: N0°34'10"E 2036.8' (grid) to set 2" aluminum cap on 5/8" x 34" rebar in centerline 20" W. Pine Stp. (30.90' Ch. – [2039.4'] W. Pine 20" – GLO); N0°35'31"E 2638.04' (grid) to 'C8' (2642.64' – GLO, 2650.56' – FJG). Measured south 5292.04' to 'C11' (5297.82' – GLO, 2687.92' – FJG). No other W. Pine stump evidence at a reasonable distance from the vertical discoloration position could be found. Accepted vertical discoloration in agreement with apparent witness #4 remains as evidence of Gibbs post. Thus set DNR Monument at found discoloration. Centerline of N-S 2-track is 21.5' West. DNR Monument accepted as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

C9 - Stamped 4" DNR Aluminum Cap on 1" x 36" long galvanized iron pipe. Set Blue Composite Post 1' North S28°W 80.98' to set Nail and Tag (N & T) in West side 22" Oak scribed 'XBT' S04°E 23.41' to set N & T in East side 5" Oak S64°E 20.98' to set N & T in North side 4" Oak N07°W 38.24' to set N & T in West side 4" Oak N60°W 10.89' to set N & T in SW side 5" W. Birch growing out of witness #4.

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
09/17/2015	N43°45'21.8696"	W84°28'02.8295"	NAD83 (2011)	2010.00

Position determined from GNSS Static observations from 2 Local OPUS Base stations adjusted by Least Squares.

I, Craig W. McVean, in a field survey on Sept. 17, 2015, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean

Craig W. McVean

Professional Surveyor's License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601

12/7/2016

Date



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on Aug. 3, 2016, and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Brian D. Ferguson

Professional Surveyor's License No.: 26454

Date