Land Corner Recordation Certificate Attachment B to 2016 Annual Grant Agreement

Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54,268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2016 State Survey and Remonumentation **Grant Agreement**

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville Township Corner **Corner Type Survey Township** Code Original Public Land E Survey Corner 16N R 1W MCL 54.202(g) R • MCL 54.262(g) R 3 10 5 **Property Controlling** S R 6 Corner Т 18 17 16 15 MCL 54.202(i) S R 7 7 MCL 54.262(h) R S 8 19 20 21 22 23 24 8 S R 9 9 28 10 30 29 27 26 25 10 Protracted Public Land Survey Corner 11 11 MCL 54.202(k) R 12 31 32 33 34 35 36 12 MCL 54.262(i) 13 В C DE F GH

Part A: Corner(s) History

C7 - 1832 - GLO - H. Parke - Set post.

- 1) Pine 20" South 15 L. 2) Pine 11" N27°W 13 L.
- 1852 GLO Resurvey A. Burt Old corner.
- 3) Hemlock 16" S64°E 37 L.
- 4) Maple 8" N42°W 18 L.
- 1901 CSR L. 1, p. 92 F. J. Gibbs Old post standing with new post at side.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

C7 - Section corner common to Sections 17, 18, 19, and 20, T16N, R1W - Based on retracement of Gibbs survey W & S. excavated sand road and found 3" diameter by 1.2' stake shadow, vertical black organics in white sand down to hardpan. No evidence of witnesses #1-4. Stake shadow fits within 0.9' of double up position from 'C8' and N 1/16 corner. Accepted shadow as original corner position and set stamped 4" DOC (MDNR) brass cap with coffee can with concrete around on 1" x 36" galvanized iron pipe - down 1'± below road grade. DOC monument accepted as a careful and faithful perpetuation of position of the original corner.

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
T16N R1W Code C7
Page 2 of 2

Professional Surveyor's License No.:

26454

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

C7 – Stamped 4" Department of Conservation (MDNR) brass cap with coffee can with concrete around on 1" x 36" galvanized iron pipe - down 1'± below grade.

N28°W 29.09' to set nail and tag in W. side of 9" Oak scribed 'XBT'

S47°W 94.33' to set nail & tag in SE side of 5" R. Maple & clump of four S46°E 37.05' to set nail & tag in SW side of 8" Cherry

Set Blue Composite Post with location tag 33' N.

N48°E 47.68' to set nail & tag in SE side 4" Oak

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
06/11/2015	N43°46'13.9656"	W84°28'02.1682"	NAD83 (2011)	2010.00
Position determined from	om GNSS Static Observa	ation from two Local OPU	JS Base stations. Adjuste	d by Least Squares.
Remonumentation Act 54.201 to 54.210d, the described in Parts A, E	t, 1990 PA 345, MCL 5 nat the corner(s) identif B, and C above, pursuant	4.261 to 54.279, and the ied and described here	ollo surie	of Michical Craig W.
Professional Surveyor Department of Natural	's License No.: 39088	naw Trail, Cadillac, MI 49	0601	OFESSIONAL SURVEYOR NO. 39088
described in Parts A, I	, ,	sented to and reviewed b	d hereon and perpetuate by the Peer Review Group	
Brian D. Ferguson		 Date		