REMON CORNER A-3, EDENVILLE TWP. LAND CORNER RECORDATION CERTIFICATE

531

13

24 25

For c	orners in	Filing Re	quirement of Act /4, Mich. F	A. 1970.		_	
Midla	nd					F MICHIG	
	(County)	Located in	: Corner Code #		HIDLA REMONUMENT	ND COUNT	
1. Pı	ublic Land Survey	T 16N R 1			NEIWINGIER I	TILLY CE	LILED
		TR_ TR_			12/28/200) 8:44 : 2	7 AM
2. Pr	operty Controlling	S T R	SURVEY &		SCOTT I		
in	Section		MONUMENTATION		REGISTE	R OF DEED	DS
	iscellaneous operty in Sec.	STR_ STR_	-FE B 2 3 2001	Register of Der	eds Stamp & File	Number	
4. Lo	ot No, Records	ed Plat	- SECTION -				
5. Pr	ivate Claims			A B		G H I	JK
I, ROD that un	NEY CLAYPOOL, in a field a	survey on June 11, 1999, do	hereby certify	2 - 6	-5 + 4 -	 3 	- 2 -
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the				3 	8 + 9	10 1	. 44 -
interior	, bureau of Land Managem	entor by a decree of a Coun	of law and/or that the	5	1 1 1	10	11 7
or the r	Wichigan Board of Land Surv	revors or by a Decree of a Co	ere in conformance with the rules ee of a Court of Law; re-established,	6 - 18 -	17 + 16	15 +	14
		overed, found as expressed b		8 - 19 -	20 + 21		77
NOTE	NOTE: Not more than 2 corners, all in the sal		me town and range, may be	9 - 1-	20 7 21	727	23
	1001000 011 1110 001	unoate,		10 - 30 -	29 - 28 -	27-	25 +
				11 - 31 -	32 - 33 -	34	35
A. De	scription of original monu	ment and accessories and	/or subsequent restoration:	13	<u></u>		
A-3	Corner common to See	ction 6 and 7 on West tow	ntine				
	Survey by Glo, 1830's	set post 24 Lks North of N	M-3, Warren Twp. Corner		0 !	BICA	No.
	Survey by MDOT, 194	13, post East of culvert 2, found corner			11,1000	The same of the sa	
	Survey by M. Hunter, v	witnesses (no date) stone and iron in monument box		:	D A CLAY	IEV D. POOL	1:3
	LORO by 3. VVIICOX, 104	una iron in monument box		e e	SALMA!	(EYOM (対D	
B. De	scription of corner eviden	ce found and/or method ap	oplied in restoring or reestablis	shing corner:		80. :241	
A-3	Corner common to Sec	ction 6 and 7 on West towr	line			H I B S	
	Found 5/8" rod in mone	ument box at position per s	survey by MDOT and LCRC b	y J. Wilcox.	AODH CLAN	and, arms	
C. De:	scription of monument for	corner and accessories e	stablished to perpetuate locate				
A-3		ction 6 and 7 on West town		ing the position o	a uie comer.		
			mure .				

Replaced rod with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

12-26-00

Revised May 14, 1971 Revised Jan., 1983

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Date

evidence of the position of the accepted corner.

Signed by / V. Surveyor's Michigan License No. 29241

N 25 Deg E, 136,38', Southwesterly bolt on Sunoco sign base N 74 Deg W, 51,28', chiseled "+" on North end culvert N 80 Deg W, 124,84', nail and MDOT disc in power pole N 32 Deg E, 57.58', nail and MDOT disc in guy pole S 27 Deg E, 112.68', USGS benchmark (#10 1934) South, 17.62 ft., M-3, T16N-R2W, existing remon corner LCRC #92 (GLO calls for 24 links, 15.84')