

**REMON. COR. H-11, MILLS TWP.
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

507

For corners in
Midland
(County)

Located in: Corner Code #

1. Public Land Survey

T 16N R 2E H-11

T R

T R

T R

2. Property Controlling
in Section

S T R ~~SURVEY &~~

3. Miscellaneous
Property in Sec.

S T R REMONUMENTATION

S T R

S T R FEB 23 2001

S T R

4. Lot No. _____, Recorded Plat _____

SECTION

5. Private Claims _____

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, RODNEY CLAYPOOL, in a field survey on July 27, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-11 1/4 Corner common to Sections 27 and 34

Survey by Glo, 1830's, set post

Survey by M. Hunter, 1965, set 3/4" pipe on line with North and South fence and on line between E-11 and I-11

Survey by J. Jones, 1984, 1997, found 3/4" pipe in monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-11 1/4 Corner common to Sections 27 and 34

Found 3/4" pipe in monument box per surveys by M. Hunter and J. Jones.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11 1/4 Corner common to Sections 27 and 34

Replaced pipe with 3/4" pipe and brass cap stamped Midland Co. Remon Cor PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

North 38.39', centerline telephone box

S 5 Deg W, 43.2', centerline 30" Elm

S 45 Deg E, 84.3, centerline 30" Willow

South, 1.7, South edge pavement

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6	5		4		3		2		1		
3													
4		7	8		9		10		11		12		
5													
6		18	17		16		15		14		13		
7													
8		19	20		21		22		23		24		
9													
10		30	29		28		27		26		25		
11													
12		31	32		33		34		35		36		
13													

Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

APPROVED LAND CORNER
P.A. 345 OF 1920
MIDLAND COUNTY

12/27/00 JLG

