APR 06 1999

	SECTION	LAND Filing	r Require	ment of A	ct 74, Mich. P	LA, 197	0						. *7	77	
For corners in MONROE		SUMMERFIELD TOWNSHIP								∡_ `	_	85		ر با	
		Located In:	SEC. I	2 Corner (Code # M-4				~	2007 2007 2007 2007	Er	OEC		7	
	(County)								٠	E CC	<i>y'</i>	မ		_ອ ່ ຕ	
Public Land Survey . . Property Controlling S.		TR_ TR_ TR_	T_75R_6 E										RECEIVED FOR RECORD 98 DEC 30 AM 8: 33		
2. Properti	-	S TR_				ł									
3. Miscella	• • • •	S TR_													
Propert	y in Sec.	S TR_				L		Re	piste	r of D	eeds	Starn) & F	le Nu	neber
4. Lot No.	, Recoi	rded Plat					1 1	. B	C	D	E F	G H	; <u>;</u>	J	K L
5. Private	Claims						2	ļ	5—	_ 5	 	- :	} -	_ į	 !-
	n S. Blanchard		AUGU	JST 21	98		3	_	\perp				$\vdash \vdash$	+	-
Ĺ.		_, in a field survey 74, Michigan P.A. of 1	on	19	do hereby mentioned in li	state nes 1	4		,	_ 8-	ا .وإ	1	0	-11	-12
and 2 above	e were in conformar	nce with regulations ar	nd rules the	erefore as re	equired in the cu	urrent	5			_	\coprod		- -		 -
manual of a	survey instructions (of the United States I Court of Law and /or t	Department that the cor	; of the inte mer points m	rtor, Bureau of rentioned in lines	Land s 3. 4	6	—1	8	17	16	1	5	-1,4]13_
and 5 above	were in conforman	ce with the rules of the	e Michigan	Board of La	ind Surveyors or	r by a	7		\sqcup	\bot	 	_ _	 		├ -├-
Decree of a below:	Court of Law; establ	lished, re-established, r	nonumente	d, recovered	i, tound as expr	08800	8	1	9	20	21	2	2	_23	-24-
-							9	_		_ _		_		Ц_	$\bot\bot$
		s, all in the same town	and range,	may be rec	orded		10		_	 29	28		7	 26	 25-
Of	n this certificate.						11	_		<u> </u>				1_	
A. Descrip	otion of original mo	nument and accesso	ries and/o	r subseque	nt restoration:		12	<u></u>		32	33		4	_] _35	
1819	GLO Surveyer	, J. Fletcher, set 1/4 se	ction post.	•			,,[لّ		<u>Ī</u> .					
	Witnesses:	W. oak 20" S77°E	•		•					-					
1061	Casa & Elask	W. oak 25" N85°! used east quarter com			na - na materia	al ac máti	1000	1156	od Fi	ile #8	181				
1961 1972		survey, File #16959, t			ne – no matema	at of Airi	1699	цач	AL I I	uc #6	101				
17/2	Witnesses:	N19°E, 101.48' t													
		S67°E, 37.88' to 2				,									
) ome		N86°W, 93.53' to	18" popul	lar											
1972	Case and Fleck Witnesses:	k, neid note. N88°W, 27.11' to	nail in tai	ienhone not	· A										
	W Huesses.	S45°E, 59.62' to 1													
		N20°E, 110.80' to													
1974	A.J. Marino, fo	ound stone: field not													
	Witnesses:	N80°W, 26.96' to													
		N60°E, 58.20' to :		•	ole										
1977	Roland L. Jack	kson, (L.C.R.C., L. 2,													
27	Witnesses:	S57°E, 57.70' to f													
		S55°E, 58.1' to fa				_									
	Added Witnes	-			in Telephone p east side powe										
					n west side pow										
1979	Kenneth L. Su	ydam (L.C.R.C., L. 2	, Pg. 378)	found R.R.	spike over sto		82 0:	304	7-17	7					
	Witnesses:	Witnesses: N10°W, 26.6', nail & shiner in electric pole S45°E, 58.67', nail & shiner in electric pole													
		North 421.10', spi			pote										
В.	Description of	f comer evidence fo	_		applied is res	storing (or re	ees	tabli	ishinq	i cou	ner:			
1997	David Arthur (Consultants, Inc., crev	w found R	.R. snike at	surface, ner L	.C.R.C.	L. 2	2. P	g. 2 0)9 .					
1998		Consultants, Inc., dug	; 1.5' x 1.5	5' x 1.0' de	ep, found R.R.	spike		,-		-					
	\wedge				found no stone										
21s A.78	THERE IS A STREET	GROUP, PA 345 O	<u>ነር 1800</u> 0 ች፣	IUNDUE 1	יים עידען אבר	CDIC A	N =	n'A'	T E	اه	مام	<u>p</u>			
	UNTY REP.		r 1330, M	WINKUE (JUNII, MI	CHIGA	17, I	J/A	1 C _					_ ,	
	REMONUME		*						•						

Land Corner Recordation Certificate - Page 2 of L - M-4, Summerfield Township, Section 12, T7, R6

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

Set 1" iron pipe with brass cap per witnesses in place of railroad spike.

Witnesses:

S36°E, 59.29' P.K. shiner in northeast face of power pole

S 58.02' P.K. shiner in northwest face of power pole

N33.02' "P.K." at centerline of Wells Road and "Bennett Road" (street to be renamed) N30°E, 85.66' "X" in south rim of concrete catch basin

N45°E, 52.09' 1" iron post

Signed by

Surveyor's Michigan License No. 2744 (

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971, REVISED MAY 14, 1975, REVISED JAN., 1983, REVISED OCT., 1995

SURVEY & REMONUMENTATION

APR 06 1999

SECTION