REMONUMENTATION

APR 2 8 1995

PAIS 10 OF 10 OF	
MONROE COMPANY, MICHAELY COMMISSION	
dato: 13 19 11 99 1993 AND CORNER RECORDATION CERTIFICATI	E
For corners in Filing Requirement of Act 74, Mich. P.A. 1970	0
MONROE Located in: BEDFORD Corner Code ## TWP.	
1. Public Land Survey	
T R	J .
2. Property Controlling S T R	
in Section S T R	egister of Deeds Stamp & File Number
Property in Sec. STR	
Lot No, Recorded Plat Private Claims	- ABCDEFGHIJKLM
5. Private Claims MONROE COUNTY REMONIMENTATION PROCRAM	2 5 4 3 2 1 1
Peer Group approved corner on 11/08/1993 per Act 345 of 1990.	3 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
(, G.B. WARNKE, JR. , in a field survey on 12/2/1994 , 19,	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	. 6 - 18 - 17 - 16 - 15 - 14 - 13 - 1
current manual of survey instructions of the United States Department of the Interior, Bureau of Land	⁷
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	8 19 20 21 22 23 24
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	10 30 29 28 27 26 35
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	"
on this certificate.	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	
(At Intersection of Dean & Secor Roads) In 1820, G.L.O. Surveyor Joseph Wampler set corner post for Sections 19, 20, 29 9 inch N.41°E. 33 links & B. Oak 14 inch N.54°W. 63 links. / O.A. Case used rail 1942. / Case & Fleck witnessed & set nail 3-8-72. / A.J. Marino notes railroad s G.B. Warnke used railroad spike & 12/18/92, per File No. 91-0473 notes bolt was was excavated, found PK nail 1 inch deep & railroad spike 4 inches deep and set witnessed.	road spike in May of pike in June of 1946. / found & referenced, area
B. Description of corner evidence found and/or method applied in restoring or reestablishing	g corner:
C-9 - On 11-02-1993, found 1/2 inch capped iron pipe (No. 19474) and witnesses of witnesses per noted G.B. Warnke Survey, File No. 91-0473. 12/2/1994, set 1 incorporate remonumentation cap inside monument box to replace found iron.	h x 36 inch iron pipe with
	RECEIVED FOR RECORD 94 DEC 16 PM 3: 33 Meri Aller REGISTER OF DEEDS MORROE COUNTY, MICH
	3 ECOR
	<u>*</u>
C. Description of monument for corner and accessories established to perpetuate locating t	
C-9 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monu- 1/2 inch capped iron pipe (No. 19474) and is accepted as the best available evid- original corner and witnesses: South 45° East 122.27' northwest corner of wood siding of building No. 8196 North 30° West 78.16' top nut of hydrant South 50° West 83.25' northeast corner of concrete block building No. 8197 South 45° West 48.89' nail/washer in north face of telephone pole North 50° East 44.75' nail/shiner in southeast face of utility pole	
	LAND SURVEYOR
Signed by Date Dece	mber 2, 1994 1
Surveyor's Michigan License No. 19474	ROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971
	REVISED JAM., 1983

LING