SURVEY & REMONUMENTATION

APR 2 8 1995 RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN COMMISSION 11/10/ 2393 County Rep. : For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 MONROE Located In: Corner Code ## BEDFORD TWP. Public Land Survey T_8SR_7E T _____ R _ T_____R T ____ R 2. Property Controlling _ R in Section _ T <u>- ;</u> _ R _ Miscellaneous Property in Sec. S **T** Register of Deeds Stamp & File Number , Recorded Plat Private Claims 1993 MONROE COUNTY REMONUMENTATION PROGRAM

Peer Group approved corner on 11/16/1993 per Act 345 of 1990. , in a field survey on , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

A. Description of original monument and accessories and/or subsequent restoration:

M-4, T8S, R7E, 1/4 Section Corner to Section 12

(On Minx Road - 1/2 Mile South of Samaria Road) (Common to A-4, TBS, RBE - Approved 7/12/1994) 1820, G.L.O. Surveyor Joseph Wampler set 1/4 post for Section 12 on the east range line. Witness: B. Oak 26 inch S.40°E. 200 links. 1942, A.J. Marino notes stone found in survey in southeast 1/4 of Section 12. June of 1943, Consumers Power survey by Turner witnessed stone. Case & Fleck witness card, dated October 1973, & 1973 survey (Liber 657, Page 46) notes stone. 1978, G.B. Warnke witnessed stone.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4 - 11/12/1993, found 1/2 inch iron pipe with crimped top 1 1/2 inches below gravel roadway and witnessed as shown below. 9/2/1994, dug up corner and found 1/2 inch pinch pipe over high point of 12 inch long red granite stone with base at approximately 30 inches deep. Dug to approximately 40 inches deep in white/gray sand. No evidence of post or other material. Set 1 inch x 36 inch iron pipe and brass remonumentation cap with stone on south side and the 1/2 inch iron pipe on north side below 1 inch iron pipe to assist in

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4 - Set 1 inch x 36 inch iron pipe and brass renonumentation cap with stone on south side and the 1/2 inch iron pipe on north side below 1 inch iron pipe to assist in stabilizing point to replace 1/2 inch iron pipe over stone & is accepted as the best available evidence of the position of the original corner & Witnesses: Fast 33.00 feet to top of Consumer Powers monument (2 inch diameter pipe with twist cap on top, in concrete,

East 28.67 feet to nail/washer in west face of electric pole

North 20° East 104.45 feet nail/washer in southwest face of southerly pole of most southerly "H" frame West +/- 2 feet to west edge of gravel, fairly large road ditch north & south along west edge of pavement

West 32.72 feet to top of Consumer Powers monument (1.0 foot out of ground)

19474

South 45° West 28.36' to top of gate nut on east end of 6 inch plastic field tile ⊒ned by ___

■veyor's Michigan License No.

Date <u>9/2/1</u>994