COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIV"

1973 DEC 29 PH 4: 03

Carie carão REGISTER OF DEEDS

For corners in			
Muskegon		Located In:	Corner Code :##
(County)			•
1. Public Land Survey		T 9N R 15W	I-4
		T R	
		T R	
		T R	
2. Property Controlling	S	T R	
n Section	S	\mathbb{R}	
3. Miscellaneous	s	T R	
Property in Sec.	S .	T R	

Register of Deeds Stamp & File Number

, Recorded Plat Lot No.

5. Private Claims

, Stephen V. Vallier in a field survey on November 24, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Iron-GTW R/R Right-of-way maps-1915+/

Show location of corner in centerline

of R/R tracks

Description of original monument and accessories and/or subsequent restoration: GLO corner set by J. Mullett, 5-30-1837

S 27 deg W

N 55 deg E

15 links

25 links

8" hemlock

12" b. ash

iron - M.C.R.C.-1955

ENE

51.13'

33.40'

66.35' pop.

NE

4" pop.

fence post

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Fd. $1\frac{1}{4}$ " iron pipe in monument box, 68.80' north of centerline of R/R bed (tracks vacated). No physical monument in second location of corner (centerline R/R)

Historical usage, documentation and evidence of corner location reviewed and ratified by Muskegon County Peer Group in Aug. 4, 1993

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2½" x 30" cast iron monument with County Survey cap (replaced found 1¼" iron pipe) S 83 deg W S 36 deg E S 16 deg W N 30 deg W N 15 deg W N 60 deg E 154.35' 171.34' 105.06' 95.98' 48.13' 91.90' 6" pop transmission 6" pop. p. pole p. pole p.pole (fd. nail pole (fd. nail (fd. nail (fd. p.k. (fd. nail s'ly side) (fd. nail w'ly side) nail s'ly side) w'ly side) ne'ly side) sw'ly side)

Stephen V Vallier Surveyor's Michigan License No.

28428

VALLIER Lend Sur... yes

STEPHEN

800 80

No. 28428

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 15