

MAR 06 1998

118EP 2052 PAGE 580

STATE OF MIGHIGAR COUNTY OF MISSINGS RECENTED MISSINGS

SECTION

Lot No.

Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

197 DEC 30 PK 3: 10

19 1		
Carrie		- n- 12
والمريح والمحروم في المريد الم		12 2 2 2 2 2
REGIST	ROF DE	ine J
		134.1

For corners in				
Muskegon	Located In:	Corner Code ##		
(County)		Meander/~		
1. Public Land Survey	T <u>10N</u> R <u>17W</u>	Corner No. (1)		
•	T R			
	T R			
dy.	T R			
2. Property Controlling	S T R	<u></u>		
in Section	S T R			
3. Miscellaneous	S T R			

___ , Recorded Plat __

Register of Deeds Stamp & File Number

1, Ralph W VanRiper , in a field survey on July 23 , 19 97 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Meander corner on the Line between Sections $25\ T10N\ R17W$ and $30\ T10N\ R16W$ and the South shore of Muskegon Lake

Post set by GLO Surveyors in 1837; B Oak 11" S11°W 40L and B Oak 10" S57°E 25L 16.69 Chains (1101.54') North of 1/4 Corner

MCRC, 1950's Witness Map and Current Witness Book do not cover this area.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 2" Pipe over 1" Iron Bar

Have records of M M Buck, F F Smith, C F Lewandoski and R W VanRiper using this corner. Accepted corner based on historical usage and documentation

50 197

POSITION OF SAID
RECORDED CORNER
REVIEWED & RATIFIED
BY MUSKEGON COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap

N 46° E 55.53' Set Spike in N side of 12" Tree

N 81° E 60.91' Set Spike in N side of Twin 22" Poplar

S 85° E 77.29' Set Spike in N side of 18" Tree

S 04° W 139.52' Set Spike in E side of 12" Maple

N 49° W 75.95' Set Spike in W side of Triple 20" Poplar

N 03° W 56.54' Set Spike in W side of 16" Tree



Signed by	Raffle	! //u	13	•
		1.0		

Dec. 26, 1997

Surveyor's Michigan License No. 16946

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983