SURVEY & REMONUMENTATION

LIREP 1951 PAGE 675

A1798 STATE OF MICHIGAN COUNTY OF MUSKEGCN RECEIVED FOR EECOND

MAR 2 1 1997

For corners in

5. Private Claims

expressed below:

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1994 PEC 23 PN 3: 50

0		, · p	A
ar	1. J. J.	شاريج سي	ر ر موروس
R	0.511 R	OF DEL	EDS

Muskegon (County)		Loc	cated In:	Corner Code ##			
1.	Public Land Survey	. т	<u>11 N_R 17 W</u>	<u>A 9</u>			
		T	R				
		7	R	·			
		Τ	R				
2.	Property Controlling	S T	R				
	in Section	S T	R				
3.	Miscellaneous	S T	R				
	Property in Sec.	S T	R				

_ , Recorded Plat

Register of Deeds Stamp & File Number

		4.5		
Ralph W VanRiper	Dec. 11	. 19 . 96		
do hereby certify that under requirements of P.A. 74, Michig in lines 1 and 2 above were in conformance with regulat	gan P.A. of 1970, the cor	•		
current manual of survey instructions of the United States Management or by a decree of a Court of Law and/or that th	s Department of the Int	erior, Bureau of Land		
above were in conformance with the rules of the Michigan	•	.*		

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	Α	В	С	D	E	F	G	Н	IJ	K	L	i
2		6		 5		4	;] 3	L] 2	_	_
Э				<u>L</u>		<u> </u>		L				
4	L	ļ 7—	L.	 8—	L,	9 —	L	 	L	1—	_1	2-
5	L	<u> </u>		<u></u>		<u></u>	<u> </u>	_				
6	Ļ	 8—	_,] 7—	1	 6—	1	5	1	4	1	3
7	_	ļ		_						_		
8	_1	 9	2	 0	2	 1	2	 2	2	3	2	4-
9,	_	<u> </u>			<u> </u>	<u> </u>				<u> </u>		
10	<u> </u>	 	2	9	2	 !8	2	 7	2	6	2	5
11	<u> </u>	<u> </u>	<u> </u>				ļ		L			
12	L	 31	_3	2—	_3	 3—	_3	 4	_3	5	3	6
	ı		I	l		l		l				

A. Description of original monument and accessories and/or subsequent restoration:

Section corner common to Sections 19 & 30, T 11 N, R 17 W, and Sections 24 & 25, T 11 N, R 18 W, Fruitland Township.

Not set by GLO Surveyors (Corner to Sections 24 & 25 in lake)

MCRC 1950's Witness Sheets, Nothing shown MCRC Current Witness Book, 1" Iron in Muskrat Lake, 310' \pm E of CL Scenic Dr., 130' \pm N of S Shore, 280' \pm E of W Shore

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Pipe in water of Muskrat Lake, water 4' + deep at corner.

Found capped steel rods by Donald G. Sandel, LS No. 25870 as shown on survey recorded in Liber 1646, Page 164. N 1°36'57" E along West Section line 437.03 Feet from Southwest corner of Section 19 AND S 87°28'31" E along South Section line 412.98 Feet from Southwest corner of Section 19 SAID

June 4, 1996

SU REVISED 1 PATIFIED

BY MUNICIPAL COUNTY

PLEE GEODIN IN ACCORDANCE

WHILE PLAT 265, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Two 2 3/4" Cast Iron Monuments with County Survey Cap at the location described above. Said point are on the North and East shore of Muskrat Lake.

SEE OTHER SIDE OF THIS SHEET FOR WITNESSES

VAN RIPER OFESSION

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 EVISED MAY 14, 1975

REVISED JAN., 1983

Surveyor's Michigan License No. ____

Set 2 3/4" Cast Iron Monument with County Survey Cap on the North side of Muskrat Lake, N 1°36'57" E along the West line of Section 19, T 11 N, R 17 W, 437.03 Feet North of the Southwest corner of Section 19.

```
Set Spike in W side of 16" Oak
North
         56.02'
N 27° E
         40.33'
                 Set Spike in E side of 14" Oak
N 41° W
                 Set Spike in S side of 14" Oak
         36.84'
                 Set Spike in E side of 4" Pine
N 25° W
         43.82'
N 14° W
                 Set Spike in W side of 15" Oak
         54.16'
N 13° W 40.54'
                 Set Spike in W side of 6" Oak
       South 30' Water's edge of Muskrat Lake
```

Set 2 3/4" Cast Iron Monument with County Survey Cap on the East side of Muskrat Lake, S 87°28'31" E along the South line of Section 19, T 11 N, R 17 W, 412.98 Feet East of the Southwest corner of Section 19

```
N 30° E
           28.20'
                     Set Spike in W side of 14" Oak
N 50° E
           15.49'
                     Set Spike in S side of 12" Oak
                     Set Spike in N side of 8" Oak
Set Spike in S side of 6" Pine
Set Spike in W side of 14" Oak
N 73° E
           14.74'
S 60° E
           20.01
S 35° E
          62.42'
S 20° E
           32.04
                     Set Spike in E side of 12" Oak
        West 30' Water's edge of Muskrat Lake
```