STATE OF MICHIGAN COUNTY OF MICHIGAN PRODUCTION OF PROOFE

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1776 0°C 23 Pi 3: 50

For corners in		•	20
Muskegon (County)	Located In:	Corner Code =##	Cally 17 Carety
Public Land Survey     .	T 11NR 17W T R T	<u>C 8</u>	the service the security
2. Property Controlling	T R S T R		
in Section	S R		
<ol><li>Miscellaneous Property in Sec.</li></ol>	\$ T R \$ T R	· .	Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L M
			2 6 5 4 3 2 1 1
		· ·	4 7 8 9 9 10 11 12 12
do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree o above were in conformance w. Court of Law; established, expressed below:	equirements of P.A. 74, Michigan P.A. in conformance with regulations are ructions of the United States Depart fa Court of Law and/or that the cornerith the rules of the Michigan Board re-established, monumented, re-	of 1970, the corner points ment of rules therefore as required tment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre monumented, recovered, four	in the Land 7 and 5 8 19 20 21 22 23 24 10 and as 10 -30 29 28 27 26 25
on this certificate		<u>.</u>	12 31 32 33 34 35 36
-	monument and accessories an	•	
1/4 Corner bet Post set by GL S 9° W, 33L)	ween Sections 19 a O Surveyors in 183	nd 20, T 11 N, R 7 (W Oak 20", N	9° E, 16 L) (Pine 30"
MCRC, Current	itness Sheets: 3 Witness Book: 1" s F. Smith, RLS No	Iron with 3 Wit	
B. Description of corner	evidence found and/or method	applied in restoring or reest	COMMISSION ablishing corner:
of Duck Lake R	over 1/2" Steel Ro oad and Nestrom Ro ion with existing	ad	Asphalt Pavement at intersection
		Later rate g	POSITION OF SAID
		CL-STEEL	RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCURDANCE WITH P.A. 345, OF 1990  Way 7,1996 Cating the position of the corner:  Cap in Asphalt Pavement.
			WITH P.A. 345, OF 1990
C. Description of monum	ent for corner and accessories	* *	May 7, 1996 Especiating the position of the corner:
			Cap in Asphalt Pavement.
N 45° E 41.50 N 55° E 63.90 S 55° E 41.23 S 35° E 68.06	Found Spike in Found Spike in Found Spike in Found Spike in Found Set Spike in Found Set Spike in Works	N side of Utilit E side of 20" Pi N side of Guy Po Side of 20" Oak Side of 8" Pine	y Pole ne le RALPH W. VAN RIPER PROFESSIONAL SURVEYOR NO.
Signed by	11.1/a 12-	· note	2/20/96
Oldinga na / 2000 (1)	<u> </u>	Date /	/-Y/U

Surveyor's Michigan License No. 16996

11503

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983