## SURVEY & **HEMONUMENTATION**

MAR 2 1 1997

LIBEP 1951 PAGE 682

STATE OF MICHIGAN COUNTY OF HUSKEGEN RECEPTION OF CORD

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE MAN 100 23 M 3: 50

	CO IVIIVII C	301014	Filing Require	ement of Act 74, Mich.	P.A. 197	Ö								
	or corners in		<b>33</b>			()			1985	مدار ماروقر	,			
M	luskegon (County)	<del></del>	Located In:	Corner Code ====	1	1600	78.47 11337	tak OF	05.FDS	بها خستانا). ).				
1.	Public Land Survey		T 11N R 17W	D 8			Sarere 1						-	
	Property Controlling in Section Miscellaneous Property in Sec.	s s	T R T R _ T R _ T R _ T R		Re	egiste	r of [	Deeds	Stam	np & l	File	Nun	nber	
4.	Lot No,			•						:				
	Private Claims					- / - [	В	CD	E F	: <u>G</u>	H	<del>                                     </del>	K	L M
in cu Ma ab Co exp	lines 1 and 2 above were rrent manual of survey ins anagement or by a decree of ove were in conformance wourt of Law; established, pressed below:  OTE: Not more than 4 on this certificate	equirements in conforma tructions of to of a Court of L. with the rules re-establish corners, all e.	of P.A. 74, Michigan P.A. ince with regulations and he United States Depart aw and/or that the corne of the Michigan Board oned, monumented, re-milion the same town and in the s	of 1970, the corner points mer d rules therefore as required ment of the Interior, Bureau or points mentioned in lines 3, if Land Surveyors or by a Decinonumented, recovered, found range, may be recorded	d in the of Land 4 and 5 aree of a und as	2 3 4 5 6 7 8 9 10 11 12 13		32-	21		3	23		-12
A.	•	ction 20	0, T 11 N, R	d/or subsequent restoration		shij	Þ							

lines and recorded in LCRC, L. 991, P. 711
Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Accepted location of 3/4" Iron Pipe as location for Center of Section.

Found 3/4" Iron Pipe over 1/2" Rod over 3/4" Pipe over 5/8" Rod in Asphalt Pavement at intersection of Duck Lake Road and Jay Road

NOTE: Removed 3/4" Rod set by Francis F. Smith

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990 7,1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap

N 10° 88.64' Found Spike in W side of 18" Oak Ε Set "PK" Nail in S side of Power Pole N 85° E 138.95' 33° E Set Spike in W side of 6" Apple 45.01' 70°° Set Spike in N side of 10" Maple 78.43' N 55° 40.44' Set "PK" Nail in W side of Power Pole N 50° 77.47 Found Spike in W side of 36" Oak

OF MICH RALPH W VAN RIPER PROFESSIONAL SURVEYOR NO. POFESSION ESSIONA TO STANK

Surveyor's Michigan License No.