## SURVEY & REMONUMENTATION

LIBEP 1951 PAGE 683

STATE OF MICHIGAN COUNTY OF MUSKEGCN PURPLY AND AUTODA

A1805

MAR 2 1 1997

LAND CORNER RECORDATION CERTIFICATE (1) 10 23 | 11 3: 50

Fo	or corners in COMMIS	SSION Filing Require	ment of Act 74, Mich. F	
	Muskegon (County)	Located In:	Corner Code ##	Carl Carle
1.	Public Land Survey	T <u>11N</u> R <u>17W</u> T R T R T R	E 8	
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
		Recorded Plat		2 6 5 4 3 2 10 11 12 3
ı, E	Ralph W VanRipe	n a field survey onNov.	, 29 , 19 96	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

3
4
7
8
9
10
11
12
31
32
33
4
7
8
9
10
20
21
22
23
24
9
10
30
29
28
27
26
25
11
12
31
32
33
34
35
36

A. Description of original monument and accessories and/or subsequent restoration:

1/4 Corner between Sections 20 and 21, T 11 N, R 17 W, Fruitland Township Post set by GLO Surveyors in 1837 (W Oak 8", S 36° W, 12 L) (Pine 10", S 49° E, 15 L)

MCRC 1950's Witness Sheets: 1" Iron Bolt, with 4 Witnesses MCRC Current Witness Book: 1/2" Rod in Mon. Box with 4 Witnesses LCRC by Francis F. Smith, RLS No. 3538, L. 991, P. 711

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Rod in Monument Box in Asphalt Pavement at intersection of Duck Lake Road and Orshal Road.

Verified location with existing witnesses.

POSITION OF SAID
RECORDED CORNER
REVIEWED & MATTIFIED
BY MUSKEGON COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

May 7, 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap in Monument Box.

N 40° E 56.68' Found Spike in E side of 8" Oak N 50° E 53.57 Set Spike in W side of 12. Oak S 45° E 86.24 Set Spike in W side of 6" Oak s 50° W 61.47' Found Spike in E side of 18" Oak 40.34' N 50° W Set Spike in E side of Utility Pole N 45° W Found Spike in E side of 16" Oak

RALPH W. VAN RIPER PROFESSIONAL SURVEYOR NO. 16948

Signed by Surveyor's Michigan License No. 16946

Date /2/20/96

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 - REVISEO MAY 14, 1975 REVISEO JAN.. 1983

41805

LIBER 1951 PAGE 683