SURVEY & REMONUMENTATION

MAR 2 1 1997

1 IRFP 1951 PAGE 684

A1806 STATE OF RICHIGAN COUNTY OF THIS RECENT

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

19% DEC 23 FN 3:50

FO	r corners in					
	Muskegon (County)	Located In:	Corner Code ≠≠	Carl	LL CLEANZE TOR OF CECOS	in the second
1,	Public Land Survey	T <u>11N</u> R <u>17</u> T R T R T R				
2, 3,	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		Register of Dee	ds Stamp & Fil	e Number
4. 5.	Lot No Private Claims	, Recorded Plat	•	A B C	D E F G H	J K L M
do in l cur Ma abr Co exp	hereby certify that under the control of the control of survey instructed the control of survey instructed the control of the	requirements of P.A. 74, Michigar e in conformance with regulation structions of the United States D of a Court of Law and/or that the c with the rules of the Michigan Bo I, re-established, monumented, I corners, all in the same tow	May 13 n P.A. of 1970, the corner points mer ns and rules therefore as required pepartment of the Interior, Bureau ocorner points mentioned in lines 3, pard of Land Surveyors or by a Deciron monumented, recovered, for what and range, may be recorded.	d in the of Land 7 4 and 5 8 19 10 30 10 30	8 9 10- 17 16 15- 20 22- 29 28 27- 32 33 34	23 24 25 35 36
A.	Description of origina	al monument and accessories	s and/or subsequent restoration	13 <u>L</u>		

Center of Section 21, T 11 N, R 17 W, Fruitland Township Not set by GLO Surveyors

MCRC 1950's Witness Sheets : 6 Witnesses

MCRC Current Witness Book : 5/8" Iron with 4 Witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Steel Rod in Asphalt Pavement, Duck Lake Road

Verified location with existing witnesses.

POSITION OF SAID RECORDED CORNER REVIEWED & DATIFIED BY MUSICION COUNTY PEER CHOUP IN ACCORDANCE WITH P.A. 345, OF 1990

may 7, 1496

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap in Asphalt Pavement.

N 10° E Set "PK" Nail in W side of Power Pole 27.82' N 33° E 52.90' Set Spike in W side of 8" Pine Found Spike in side of 28" Oak S 20° E 46.90' Found Spike in side of 10" Oak 41.00' South Found Spike in side of 28" Oak S 60° W 52.63' 44.42' Set Spike in W side of 12" Oak

VAN RIPER PROFESSIONAL SURVEYOR NU. 16946 POFESSION

Signed by _ Surveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

