SURVEY & REMONUMENTATION

MAR 2 1 1997

LIBER 1951 PAGE 685

COUNTY OF FUSKEGON

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

W// W// 23 M/ 3:50

22.00 EFUS

Muskegon Located In: Corner Code ## 1. Public Land Survey T 11N R17W F 9	
•	0F D
TR	
T R	
2. Property Controlling S T R	
in Section S T R	
3. Miscellaneous S T R R Register of Deeds Stan	amo
Property in Sec. S T R	

& File Number

1.	L	ot 1	٧٥.	_		,	Recorded	Plat	
_	_		_		_				

Private Claims

Ralph W VanRiper in a field survey on 19_9.6 Nov. 29 $do\ hereby\ certify\ that\ under\ requirements\ of\ P.A.\ 74, Michigan\ P.A.\ of\ 1970, the\ corner\ points\ mentioned$ in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1/4 Corner between Sections 21 and 28, T 11 N, R 17 W, Fruitland Township Post set by GLO Surveyors in 1837 (Pine 18", S 36° W, 12 L) (Pine 16" N 9° E, 33 L)

MCRC 1950's Witness Sheets, Iron Pipe with 2 Witnesses MCRC Current Witness Book, 1 1/4 Iron P. with 5 Witnesses LCRC by Ralph W. VanRiper, RLS No. 16946, L. 1230, P. 367

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Rod over 3/4" Pipe in Monument Box in Asphalt Pavement of Bard Road

Verified location with existing witnesses

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSICEGOR COUNTY PEER GROUP III ACCORDANCE WITH P.A. 345, OF 1990

May 7, 1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap in Monument

Found Spike in E side of 10" Oak 44.82' North Set Spike in E side of 10" Oak N 5° 38.33' N 60° E Found Spike in S side of 24" Oak 63.95' s 30° E Found Spike in W side of 10" Oak 43.20' 37.57' Set Spike in W side of 10th Oak South

Found Spike in E side of quad 8" Maples S 15° W 36.28'

Signed by _ Surveyor's Michigan License No. 1694

POFESSIONA Date 🗸

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISEO JAN., 1983

RALPH W

VAN RIPER

SURVEYOR