

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Muskegon
(County)

Located In:

Corner Code ##

Carrie Carter
REGISTER OF DEEDS

1. Public Land Survey T 11N R 17W K-4
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Donald G. Sandel, in a field survey on August 3, 1993,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- (1) GLO set quarter Section post June 30, 1837
Beech 8" S30°W 0.21 chs; Sugar 13" N30°E 0.07 chs
- (2) MCRC (1950's) witnesses: WSW 40.5' 24" E; NE 63.5' 10" E;
SE 47.0' 40" Cottonwood
- (3) Found 1" pipe from MCRC witnesses-Sandel Surveying July 2, 1979
N45°W, fd. nail SW side, stub T. pole, 44.87'; N65°E, NW corner
N. Headwall 22.20'; S21°E, set nail NE side, 16" White Pine, 66.35';
S76°W, set nail SE side, 10" B. Oak, 108.20'; S75°E, set nail N side,
18" W. Pine, 110.48"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (1) Found 3/4" rebar in center of monument box at intersection of Lorensen
& Dame Roads (paved area). Roads, culverts & curbing all appeared to be
new construction. Previous witnesses were destroyed, as none were found.
- (2) Historical usage, documentation, and evidence of corner location reviewed
and ratified by Muskegon County Peer Group, July 15, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" x 20" cast iron "County Survey" monument in monument box, in place
of found 3/4" rebar; witnessed as follows:
S 45°W, set, nail, SE side with County tag, T. pole, 59.61'
S 63°W, found, post N. edge, stop sign post, 43.77'
N 42°W, set, nail SW side with County tag, T. pole, 59.39'
N 63°E, found, post S. edge, stop sign post, 44.16'
S 55°E, set, nail N. side with County tag, 9" White Pine, 76.87'
S 39°E, set, nail W. side with County tag, 9" White Pine, 74.34'

Signed by Donald G. SandelDate 28 December 1993Surveyor's Michigan License No. 25870