

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N. R. 25 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 2-35

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 1-5-62 with Arne Metsa, District Forester

WITNESSES TO CORNER..... 16" Cedar Stump (dead) (1/4 S NBT) S 75°W 39 links



13" Cedar Stump (NBT) S 7° E 68 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old Y. Birch Stump which was marked as the original Corner, with Hemlock B.T. bearing N 4° W, 18 links, stump in poor condition.

Found overgrowth with inverted scribe marks very plain.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10-28-63
REGISTERED LAND SURVEYOR
✓ Billy D. Buckler