## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.\_43. NR \_ 25 \_ W \_

			KarquetteCOUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 19,20,29,30
DESCRIPTION	OF	CORNER	MONUMENT_1#_Pipe_with_4#_Breas_cap
WITTNESSES	то	CORNER	_ 7"_ Ceder = \$ 85 W = 20 Linke :
			_4" Cedar = 8 70 E = 26 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Two original B.T.'s in place, in poor condition.

Corner was placed and witnessed October 24, 1951.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 11/1/51 \_