

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T43 & 44NR 25 W ..

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 2, 35, 36 ..

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap ..

WITNESSES TO CORNER 15" Cedar S 75° E 40 links ..

7" Cedar S 23° E 45 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced Section Corner.

1" Iron Pin in place set by Victor Larson, Escanaba, from original B.T.'s
in 1925.

No positive evidence of B.T.'s.

Distance checks to swamp edges East and South. Old blaze line South, West
and East. Corner lies 1/2 ch. West of N-S trail road.

Corner placed and witnessed June 5, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 7/25/56
REGISTERED LAND SURVEYOR