

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 43 N. XX R. 25 W.	6-3
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S. R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S. R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER _____

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 28, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

SE Sec. corner of Sec. 4
Mich. Dept. of Conservation
Oct. 10, 1950
Set 1" pipe w/4" brass cap
One original B.T. still in place but nearly gone. Also homesteaders clearing S & E line fence south.
New witnesses: 12" Basswood - N65°E - 5 Lks.
6" Basswood - S50°W - 12 Lks.
9" Basswood - N72°W - 41 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Re-witnessed Monument as found. All three Conservation Dept. N.B.T.s are in place and living but one is nearly dead and the other two have large cracks in the trunk and will probably not last many more years. Stp. in place for N.W. O.B.T.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Brass cap Conservation Dept. monument
Tw. 9" apples (not marked) - S67°E - 266.0'
6" maple - S32°W - 36.1'
5" maple - N28°W - 33.2'
10" maple - N 9°E - 46.95'
(o.b.t. stp.)
20" maple stump - N26°W - 13.4'

SIGNED BY David B. Babbitt DATE 9-12-84

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: