

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette  
(County)

Located In:

Corner Code ##

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S 32 T 43N R 25W 12  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, David B. Babbitt, in a field survey on May 3, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

12. South 1/16 corner of Section 32. No previous record.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

12. This corner position is mid-point on line between the south 1/4 corner and the center of Section 32. This position falls near the westerly edge of a large pond in water about 3 ft. deep. No marker was set at the corner position but two witness monuments were set as follows. One DNR monument was set on the N-S 1/4 line 675.0 ft. south of the 1/16 corner position and one was set on the 1/16 line 100.0 ft. west of the 1/16 corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR Monument  
Set on the N-S 1/4 line 675.0 ft.  
south of the S1/16 cor. position.  
8" cedar, N44W, 9.45'  
7" cedar, N14E, 12.7'  
12" cedar, S76E, 15.65'  
8" cedar, S10W, 11.95'

DNR Monument  
Set on the 1/16 line 100.0 ft. west of the  
S1/16 cor. position.  
6" cedar, N41E, 9.8'  
7" cedar, N80E, 13.3'  
5" cedar, N34W, 5.4'  
12" cedar, S30W, 16.1'

Signed by David B. Babbitt Date 8-1-88  
Surveyor's Michigan License No. 21558