

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> N. S., R. <u>23</u> E. W.	<u>M-5, M-6</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on October 20 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

M-5 N.E. section corner - Section 13; Wood Post, Birch 6 - S53°E - 25 lks.; Do. 8 - N40°W - 8 lks.; Hemlock 10 - S55°W - 16 lks.; Birch 9 - N35°W - 8 lks.

M-6 East 1/4 corner - Section 13; Wood Post, Sugar 8 - S36°E - 24 lks.; Sugar 9 - N59°W - 20 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-5 Found old square post beside older post point. Three trees nearby with old blazes facing post. Not of record but measurements north, south and west to known corners are all reasonable. Replaced old post point with D.N.R. monument.

M-6 Set M.P.O.L. between the N.E. and S.E. section corners of Section 13.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 1" pipe, 4" aluminum cap; 4" Cedar - N25°W - 23.2'; 7" Cedar with old blaze facing corner - S79°E - 11.3'; 5" Cedar - S11°E - 18.3'; 11" W. Pine - S18°W - 31.9'.

M-6 1" pipe, 4" aluminum cap; 6" Maple - N46°E - 24.9'; 9" Maple - S66°E - 24.7'; 8" Ironwood - S30°W - 21.0'; 8" Maple - N25°W - 11.6'.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY David B. Babbitt CHIEF OF SURVEY PARTY DATE 1-26-81  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558