MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_ 44_ NR 26 .W.

			Marquette COUNTY
DESCRIPTION	OF	CORNER	Section_Corner_common_to_Sections_16,17,20,21.
DESCRIPTION	OF	CORNER	MONUMENT_1"_Pipe_with_4" Brass_cap
WITTNESSES	то	CORNER	_ 8"_ CederN_8_W = 6 Links
			8" Qedar = 8 86 E = 22 Links
			_ 10" Cedar + 8 10 N - 19 Links
			·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by the Forestry Division survey crew, while making a partial resurvey of this Township. One original B.T. still in place, in good condition.

Corner was placed and witnessed February 12, 1952.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 3/24/52