

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44N N.R. 30W


Dickinson COUNTY

DESCRIPTION OF CORNER Section corner common to sections 25-26-35-36

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9/21/62

WITNESSES TO CORNER..... 9" Cedar (S35 NBT) S34°W, 19½ links



6" Cedar (S26 NBT) N23°W, 36 links

8" Cedar (S36 NBT) S51°E, 31½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one cedar stump bearing N20°E, 40 links. Also found an extra tree scribed "S26" bearing N35°W, 16 links. (no record) Found 24" W. Pine Line tree about 10 chains south of corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 17, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler