

# SURVEY & REMONUMENTATION

MAR 13 1998

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

1997 DEC 26 PM 12:44

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 25W

G-2

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous

S      T      R     

Property in Sec.

S      T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims         

*Patricia A. Monley*  
REGISTER OF DEEDS *pm*

LIBER

2 PAGE 13

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on AUGUST 5TH, 19 97, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

G-2: Quarter Corner common to Sections 3 and 4.

1852: Martin M. Hall's original subdivision survey notes describe the corner monument as a Spruce Pine post referenced by:

12" Spruce Pine S55W, 16 L 10" Spruce Pine N38E, 23 L

1942: Survey field notes from M.C.R.C. F.B. #712 (No pg. given) indicate the corner as a set 1" Iron Pipe and Jack Pine Post. Heilala notes that, "All corners (set at this time in this township by the M.C.R.C.) were set in accordance with the U.S. Field Notes where such notes could be used. Locations of lakes, rivers, sloughs, swamps, and hills were considered in locating the corners, and I believe they are set as close as possible to the original locations. In a few places very old squared trees were found decayed and windfallen, but in most places all evidence has been destroyed by forest fires." Established references:

5" J. Pine N67E, 14.8' 9" J. Pine N66W, 61.0'

No Date: The M.C.R.C. Government Corner Index Book (F.B. #643 - Sec. 3) indicates the corner as a 1" Iron Pipe and Jack Pine Post referenced by:

5" J. Pine N67E, 14.8' 9" J. Pine N66W, 61.0'

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-2: 1997: No original corner evidence found. Found and accepted a 1" diam. Pipe undisturbed and plumb. Found existing references as described in Part C below. Checked Line Call (South, 66', descend 20' course S.E.). Measured call: South 66', descend 20' S.E. Checked Line Call (South, 132', descend bank 60'). Measured call: South 132', descend bank 60'. Checked Line Call (South, 478.5', bend of stream 10 L [6.6'] West of line). Measured call: South, 470', bend of stream 8' West of line. Distance North is 2701.31' and distance South is 2629.41'.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-2: 1997: Replaced found 1" diam. Pipe with a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Measured existing references:

9" J. Pine N40E, 4.12' (to set d.h. nail)

11" J. Pine N67E, 15.19' (to set d.h. nail) (fd. scribed butt blaze) (M.C.R.C. NBT)

7" W. Pine S05E, 20.28' (to set d.h. nail)

5" W. Pine S75W, 50.69' (to set d.h. nail)

Green Steel Sign Post w/ Yellow Survey Marker Sign N.E., 3'

Note: Bearing trees were found with face blazes only unless otherwise noted. Butt and side nail blazes with d.h. measuring nails were added, and stamped B.T. Tags affixed.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4	●	3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

*Larry J. Bussone*  
DATE 12/18/97



Signed by Gerald W. Carlson

Date 12-18-97

Surveyor's Michigan License No. 24589