

1993

COMMISSION

JOB NUMBER: 93300
SHEET NO. : 1-381
For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

REGISTERED
1993 DEC 29 AM 10:35
MARQUETTE COUNTY
RECEIVED FOR RECORD

MARQUETTE
(County)

Located In:

Corner Code ##

1. Public Land Survey

T45N R 25W

MC M-11/12

T45N R 24W

MC A-11/12

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

#4

1 28
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, GERALD W. CARLSON, in a field survey on Saturday, December 18, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

MC M-11: Meander Corner south of Section Corner common to 1954 - R.J. Brotherton surveyed the line from the 1/4 Sections 25 and 36, T45N-R25W and Sections 30 and 31, T45N- corner to Sections 31 & 36 North to an iron on the North R24W. 1844: William A. Burt's original survey notes describe shore of Bass Lake. the corner monument as a 5" Cedar referenced by:
18" Hemlock S85W, 10 1
(South shore of Bass Lake)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found 1 1/2" pipe 0.3 ft. high 1.5 ft. South of high water mark. This location proved impractical to set a marker. Replaced a capped iron Benson Forest FS No. 25849 for a W.C.M.C. 15' +/- South of the water's edge on the South shore of Bass Lake. The distanced to found iron pipes in the 1993 survey matched almost exactly to the measurements of the R.J. Brotherton survey in 1954 across Bass Lake to the North.
Peer group ratification 12-13-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Replaced a Benson Forest iron with a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:
6" Cedar N27E 5.91 ft.
8" Hemlock S33E 16.52 ft.
9" Hemlock S68W 16.06 ft.
11" Hemlock N78W 12.72 ft.
Monument is flush with existing ground.
Bk. 4, Pg. 38



Signed by Gerald W. Carlson

Date 12-28-93

Surveyor's Michigan License No. 24589