

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 45 NR 26 W
T 45 N R 27 W

Marquette COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 30, 31, 25, 36

DESCRIPTION OF CORNER MONUMENT Steel Fence Post

WITNESSES TO CORNER 8" Cedar - S 17 E - 22 Links

8" Cedar - S 43 W - 11 Links

10" Cedar - N 11 E - 20 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division Survey crew, while working
in this area. Corner had been previously located by B.L. Shjonberg, Registered Land
Surveyor, who placed the Steel Fence Post in the corner location. One original B.T.
still in place, in good condition.

Corner was witnessed October 25, 1950.

SURVEYORS SEAL

SIGNED John C. Shjonberg DATE 1/15/51
REGISTERED LAND SURVEYOR