Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 45-46 M.R. 26Vi

| | | Marquette | COUNTY |
|-----------------------------|----------------------------------|-----------|----------|
| DESCRIPTION OF CORNER | 1/4 Corner between Sections 5-32 | | <u> </u> |
| CORNER HONUMENT | l" Pipe with 4" Aluminum Cap. | _ | |
| DATE MONUMENT PLACED AND WI | TNESSED 6/21/67 | | |
| WITHESSES TO CORNER | 18" Jack Pine (1/4 NPT) 112°W 4 | 2.51 | |
| CIRCLE CORMER REGISTERED - | D | | |

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Section Corners.

No evidence of Original Corner.

SURVEYOR'S SEAL

Sielly D. Suckler DATE 10/25/67