

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette

(County)

Located in:

Corner Code #

1. Public Land Survey

T 45N R 27W MC H13-113

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Jul 09 2001

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
 (MC H13-113) Meander corner on Township line on west side of Kates Lake. Remonumented in the original position from original W.Pine BT and recorded in 1957 by Billy O. Buckler, RLS. 1" pipe with 4" brass cap. 16" Soft Maple S13E 62 links, 13" Tamarack N66W 78 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC H13-113) Recovered the 1957 monument as described, in good condition, projecting about 2'a.g., and at record bearing and distance from the remains of the original W.Pine BT, found N44W 27.9', being a stump with "BT" and notch plain, and from the 1957 witnesses: the maple a dead stub and the tamarack in good condition with overgrown blaze. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 (MC H13-113) Fd. 1" ID iron pipe with 4" brass MDOC cap. Blazed and scribed:
 7" Balsam N33E 2.8' "MC NBT"
 7" Balsam S19E 32.3' do
 8" B.Spruce N16W 40.9' do
 16" Tam. N56W 50.8' (the 1957 NBT)
 Sq'd cedar post adjacent. Bearings are magnetic. Distances to notch in lower blaze.



Signed by Stephan J. Szyszkoski

Date 8/8/01

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources - Forest Management Division