

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Marquette

(County)

Located In:

Corner Code 47

| | | | | | | |
|---|---------------------------------|---|-----|---|-----|----|
| 1 | Public Land Survey | T | 45N | R | 28W | C3 |
| | | T | | R | | D4 |
| | | T | | R | | D5 |
| 2 | Property Controlling in Section | S | 8 | T | R | 9 |
| | | S | | T | R | |
| 3 | Miscellaneous | S | | T | R | |
| | Property in Sec. | S | | T | R | |

Register of Deeds Stamp & File Number

4 Lot No. _____ Recorded Plat _____
 5 Private Claims _____

I, Keith Sackett, in a field survey on March 12, 1990, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

| | | | |
|-------------------------------|--|--|--|
| C3 | D4 | D5 | 9 |
| Found 1" ID 4" out of ground. | Not set on original survey nor subsequently, apparently. | Original monument and accessories not found. | Not set on original survey nor subsequently, apparently. |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

| | | | |
|-------------------------------|---|------------------------------|---|
| C3 | D4 | D5 | 9 |
| Restored at found 1" ID pipe. | Established at intersection of 1/4 lines. | Restored midway and on line. | Established during section subdivision. |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

| | | | |
|--|--|--|---|
| C3 | D4 | D5 | 9 |
| 1" ID x unknown length 4" out of ground. | Set 1" ID x 32" iron pipe w/plastic cap. | Set 1" ID x 32" iron pipe w/plastic cap. | Set 1" ID x 6' iron pipe w/plastic cap. |
| 6" cedar S46E 32.0' s8, NBT | 6" spruce S57E 5.9' 1/16s, BT | 4" j. pine vest 7.0' 1/4s, NBT | 5" spruce N50W 93.7' 1/16s, BT |
| 4" cedar S63W 3.2' s7, NBT | 5" spruce N20W 12.8' 1/16s, BT | 4" j. pine S64E 16.5' 1/4s, NBT | 5" cedar S14E 91.5' 1/16s, BT |
| 14" cedar N03W 22.2' s6, NBT | 4" spruce S22W 18.9' 1/16s, BT | 4" balsam N65E 18.2' 1/4s, NBT | 5" spruce N22E 130.4' 1/16s, BT |

Signed by Keith Sackett Date August 27, 1990

Surveyor's Michigan License No. _____

19006

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1978
 REVISED JAN. 1983

